DRB-000400 99	ATC 035 7B X X LABL ADJ COV PRCS	B10 RAMP BUMP	KPFB37313 F-150	MAIL	0 15
VEHIC	LE DESCRIPTION - 150 2023 F-150 4X4 SUPERCREW 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO W/TO	B10 RAMP BUMP EXTERIOR OXFORD WH INTERIOR DARK SLATE • AUTO HOLD • BLIS W/CROSS-TRAFFIC ALERT • DYNAMIC HITCH ASSIST • FORDPASS CONNECT™ 4G HOTSPOT TELEMATICS MODEM • LANE-KEEPING SYSTEM • MYKEY® • POST-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION ASSIST W/AEB • REVERSE BRAKE ASSIST • REVERSE BRAKE ASSIST • REVERSE SENSING AND REAR VIEW CAMERA • SELECTSHIFT® • PRICE INF BASE PRIC TOTAL VEH	PF B37313 ITE CLOTH 40CONSLE40 SEETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM SOS POST-CRASH ALERT SYST TIRE PRESSURE MONIT SYS URREATY SYR/36,000 BUMPER / BUMPER SYR/60,000 POWERTRAIN SYR/60,000 HYBRID BATTERY ORMATION E \$50,22 10NS/OTHER INCLE & OPTIONS/OTHER \$525	SRP Conto Contract solution Contract solution C	my and En Standard Pi 70 MPG. Th MPGe. Value do not refle based on Ei 6 222 5 highway gal Fuel Economy Fuel Economy This vehicle emits 495 distributing fuel also con- or gets 28 MPG and costs \$2.95 per gallon. This is is is sins are a significant GOV nd compare vehicles STAR SAFETY $\bigstar \bigstar$ ontal, side and rollover. vehicles of similar size and at $\bigstar \bigstar$ at $\bigstar \bigstar$
	RAMP ONE				raffic Safety Admini ar.gov or 1-888-327-4
	CO59 RAMP TWO	RAIL	L MSRP \$57,190.00 Whether you decide to lease or finance vehicle, you'll find the choices that are in for you. See your dealer for details or vis www.ford.com/finance.	your right	nicals including engine e
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not ir options or accessories are not	soline, License, and Title Fees, ncluded. Dealer installed B574 A	7BX X 335 000400 02 22 24	To minimize exposure, avoid breathing vehicle in a well-ventilated area and we For more information go to www.P65W	g exhaust, do not idle the gear gloves or wash your

05/20/2024

