HRM-003144 TX	4-REBILL, NB, 203144, SD142 169 CLE DESCRIPTION	990			AMP BOOK EXFL ROTA	0 1538
	2025 XL FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR OXFORD INTERIOR BLACK (SR A79 WHITE DNYX-MED DK SLATE TRI	941	EPA DOT Fuel Economy Fuel Economy	
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CARGO BOX TIE DOWN HOOKS • DAYTIME RUNNING LAMPS • DOOR HANDLES - BLACK • EASY FUEL® CAPLESS FILLER • FLEXBED™ STORAGE SYSTEM • GRILLE - BLACK MESH • HEADLAMPS-LED AUTO ON/OFF • LED REFLECTOR HEADLAMPS • MANUAL LOCKING TAILGATE • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 100A OPTIONAL EQUIPMENT/OTHER 2K TRAILER HITCH RECEIVER FLR LNRS W/CARPETED MATS 50 STATE EMISSIONS FRONT LICENSE PLATE BRACKET	In the second se	BASE TOTAL TOTAL	BELT-MINDER CHIM LATCH CHILD SAFET SECURILOCK® ANTI SECURILOCK® ANTI TIRE PRESSURE MO EB WARRANTY 3YR/36,000 BUMPEF 5YR/60,000 POWERT 5YR/60,000 POWERT SYR/60,000 HYBRIE SYR/100,000 HYBRIE -COMPONENTS IF EC	E TY SYSTEM I-THEFT SYS NIT SYS A / BUMPER RAIN DE ASSIST D UNIQUE	Annual fuel Cost Annual fuel Cost Atual results will vary for many reasons, Atual cost Atual	Fuel Economy a This vehicle emits 234 distributing fuel also cr MPG and costs \$9,50 or gallon. MPGe is main the change and smoge OV compare vehicles TAR SAFETY $\bigstar \bigstar $ al, side and rollover. nicles of similar size and $\bigstar \bigstar $ act. $\bigstar \bigstar \bigstar $
	RAMP ONE RA5B		TAL MSRP \$28,3 Whether you decide to leas	865.00	3FTTW8	A36SRA79941
	This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not incli options or accessories are not in the state of the stat	ne Federal Automobile Iline, License, and Title Fees, uded. Dealer installed SD1	vehicle, you'll find the choic credit for you. See your dealer for www.ford.com/finance.	es that are right details or visit	WARNING: Operating, servicing an vehicle can expose you to chemica lead, which are known to the State of Cali To minimize exposure, avoid breathing ex vehicle in a well-ventilated area and wear For more information go to www.P65Warn	als including engine e ifornia to cause canc chaust. do not idle the

