	6B2A8WORABLADJCOVPRCSB10RAMPBUMP	3FMTK3SU0PMA86325 MUSTANG	SH 022132 6413/6736
COA-OUSTOS OR UT I FOR A COARDON OF THE CORRECTION OF THE CORRECT	ABL ADJ COV PRCS B10 RAMP BUMP TON TACANAGE AND	PM A86325 TERIOR VAPOR BLUE METALLIC RYAPOR BLUE METALLIC BUK PERFORATED ACTIVEX AD CHARGER EM, 10 SPKR V(3-YR INC) E PEDAL DRV NCONNECTOR PEDAL DRV NCONNECTOR CONNECTOR RAKING SYS CHRG CAPABL	SH 022132 6413/6736 EPAC Fuel Economy and Environm Fuel Economy Image: State Construction of the environment of
333			Rollover ★ ★ ★ ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), with 5 being the Source: National Highway Traffic Safety Administration (NH www.safercar.gov or 1-888-327-4236
	RAMP ONE CA42 RAMP TWO CONVOY ITEM #: 74-J60F O/T 2	TOTAL MSRP\$52,285.00Image: State of the	3FMTK3SUOPMA86325
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	I384 R 6B 2A8 335 003189 02 22 24	California to cause cancer and birth defects or other reproductive harm. To or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

05/14/2024

