CHI-004253 TX 9-NORMAL,	NB,104253,RC061 1399 12024031	5 4288 UTC U W T2 CERT CERT CERT TRD RAMP BUT	U22338 g
Image: Control of the second secon	ION CORCERS XPLORER XLT RWD WHEELBASE COBOOST 1-4 ENGINE COBOOST 1-4 ENGINE COBO	5 4288 CERTICERTICERTITED RAMPBUR RG A566755 RG A566755 TERIOR ICONIC SILVER METALLIC ERIOR EBONY/LT SLATE ACTIVEX SEAT SSS LOCK/ BUTTON START EAKERS DISC/ABS 0 [™] NECT T SINSORS RA SAFETY/SECURITY • ADVANCETRAC™ WITH RSC® • AIRBAG-DRIVER/PASS KNEE • AIRBAGS - DUAL STAGE FRONT • AIRBAGS - DUAL STAGE FRONT • AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT • AIRBAGS - SAFETY CANOPY® • INDIV TIRE PRESS MONIT SYS • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • PERSONAL SAFETY SYSTEM™ • SOS POST-CRASH ALERT SYS™	ATE CAMP BOOK EXFI ROTA D22330 921/2254 Image: Anticipation of the sector of
XLT SPORT APPEARANCE PACKAGE 1,995.00 .20" CRBN GRAY-PTD 10-SPK WHLS FRONT LICENSE PLATE BRACKET NO CHARGE	RAMP ONE	TOTAL MSPD \$46.325.00	Frontal Driver * * * * * * * * * * * * * * * * * * *
	CHTB RAMP TWO CONVOY	TOTAL MSRP \$46,325.00 Whether you decide to lease or finance you decide to	
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	Ford Credit for you. See your dealer for details or visi www.ford.com/finance. RC061 N RB 2X 425 004253 03 06 24	warning: Operating, servicing and maintaining a passenger vehicle vehicle can expose you to chemicals including engine exhaust, carbor lead, which are known to the State of California to cause cancer and birth d To minimize exposure, avoid breathing exhaust, do not idle the engine excervehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202403154288

06/03/2024

