| CHI-005650 _{SC} | 9-NORMAL, NB, 105650, SE061 135 0 | 0 120250514 1836 | UTC U W SC CERTCERTCERT TRD RAMPBUMPCAM | DBOOKEXFLROTABATT 02 717/ |
|---|--|---|---|---|
| ford.com | HICLE DESCRIPTION EXPLORER 2025 EXPLORER ACTIVE RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION | INTERIOR | SG CO7352 CK METALLIC ACTIVEX SEATS | EPA DOT Fuel Economy and Env Fuel Economy MPG. The be |
| STANDARD EQUIPMENT INCLUDED EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER .18" SILVER PAINTED ALUM WHLS .P255/65R18 A/S BSW TIRES 50 STATE EMISSIONS ACTIVE COMFORT PACKAGE .REMOTE START SYSTEM .LED FOG LAMPS .UNIVERSAL GARAGE DOOR OPENER HEATED STEERING WHEEL .LED SIGNATURE LIGHTING .8-WAY POWER PASSENGER SEAT INFLATOR KIT-DELETE SPARE TIRE | NTERIOR 9.12.3" LCD DIGITAL CLUSTER 100CH UP/DOWN DR/PASS WIN 3RD ROW - 50/50 FOLD FLAT 0.00L ILLUM VIS VANITY MIRR 0.00L ILLUM VIS VANITY MIRR 0.00L ROW HEATED SEATS 0.00L ROW HEATED SEAT 0.00L ROW HEATED SEAT 10.00L ROW HEATED SEAT ND CHARGE 3,410.00 | TOTAL VEH | AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® INDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM™ SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST (MSRP) DRMATION | Image: Additional state of the state of |
| | ITEM #: | CONVOY | LMSRP \$44,790.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit | www.safercar.gov or 1-888-327-42 |
| | This label is affixed pursuant to the Information Disclosure Act. Gasolin State and Local taxes are not incluc options or accessories are not incl | Federal Automobile ne, License, and Title Fees, led. Dealer installed SE061 N | www.ford.com/finance. RB 2X 560 005650 05 06 25 | lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge |

