HRM-008423 _{MA}	9-NORMAL, NB, 108423, SC201 93	56	UTCUWMACERTCERTCERTTRDRAMPBUMP	CAMPBOOKEXFLROTA 7113/
Image: constraint of the second state of the second sta	<section-header><section-header></section-header></section-header>	EXTERIOR OXFORD WHIT INTERIOR BLACK ONYX	SR A67293 TE MED DK SLATE TRI MED DK SLATE TRI SAFETY/SECURITY AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME LATCH CHILD SAFETY SYSTEM ELATCH CHILD SAFETY SYSTEM SECURILOCK® ANTI-THEFT SYS TIRE PRESSURE MONIT SYS DIRE PRESSURE MONIT SYS MENTION SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN SYR/60,000 POWERTRAIN MENTION ME	CAMP BOOK [EXFLIRICATA] 71134 FIGE Fuel Economy Fuel Economy MPG Strail Pickup Small Pickup Strail Pickup Strail Pickup </th
				Side Crash Based on the risk of rollover in a single-vehicle crash.Front seat * * *MatrixImage: Crash * * *Based on the risk of rollover in a single-vehicle crash.
	RAMP ONE	TOTAL	MSRP \$29,010.00	Star ratings range from 1 to 5 stars (★★★★), wit Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42 3FTTW8BA7SRA67293
	RAMP TWO	RAIL Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	the Federal Automobile oline, License, and Title Fees, cluded. Dealer installed SC201 N	www.ford.com/finance.	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the even vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

