HRM-010668 _{NJ}	9-NORMAL, NB, 010668, SC251 21 CLE DESCRIPTION	097			AMPBOOKEXFLROTA	0 4141
	2025 TREMOR AWD 121" WHEELBASE 2.0L ECOBOOST ENGINE AUTOMATIC TRANSMISSION	INTERIO	ONIZED GRAY METALLIC	009		Small Picku MPG. The b
STANDARD EQUIPMENT INCLUDED A EXTERIOR ACOUSTIC-LAMINATE WINDSHLD BLACK FORD OVALS BOX LIGHTING-LED CONVENTINAL SPARE ENCLOSED BED STORAGE FLEXBED [™] STORAGE SYSTEM HEADLAMPS- LED WITH SIGNATURE LIGHTING HOOD AND DOOR GRAPHICS POWER HEATED MIRRORS POWER SLIDING REAR WINDOW SKID PLATE TOUGH BED® SPRAY-IN LINER TOW HOOKS TRAILER TOW HITCH INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 602A OPTIONAL EQUIPMENT/OTHER POWER MOON ROOF S0 STATE EMISSIONS T [™] MACH DARK ALUM WHEEL REAR PARKING SENSORS DEALER INSTALLED OPTIONS SecuriCodeÖ Keyless-Entry Keyp	International States of Contract of Contra	BA TO TO	SIST2.0 • PERIMETER ALARM • SECURILOCK® AN • SECURILOCK® AN • TIRE PRESSURE M • START • START • START • SYR/36,000 BUMPE • 5YR/60,000 POWEF • 5YR/60,000 POWEF • 5YR/60,000 POWEF • SYR/60,000 POWEF • SYR/100,000 HYBRI CRN UNIT	ME ETY SYSTEM A TI-THEFT SYS ONIT SYS ER / BUMPER RTRAIN IDE ASSIST ID UNIQUE	4.3 gallons per 100 miles Annual fuel COST \$2,300	Economy 8 iicle emits 387 ing fuel also cr ng driving cod d costs \$9,50 h. MPGe is m ge and smog. e vehicles SAFETY ★ ★ ★ similar size a ★ ★ ★ similar size a ★ ★ ★ crash. ★ ★ ★ 1 crash.
	RAMP ONE CU2G RAMP TWO	CONVOX	Whether you decide to lea	,165.00 ise or finance your	3FTTW8NA7SR	A77009
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not in	16-Z200 O/T 2 For the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed S	vehicle, you'll find the cho d Credit for you. See your dealer fo www.ford.com/finance.	r details or visit	WARNING: Operating, servicing and maintative vehicle can expose you to chemicals includi lead, which are known to the State of California to To minimize exposure, avoid breathing exhaust, do vehicle in a well-ventilated area and wear gloves o For more information go to www.P65Warnings.ca.g	ling engine e cause cance o not idle the

