2024 F35     XL 179"     ford.com     STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHAIN     STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHAIN     STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHAIN     • HEADLAMPS - AUTOLAMP (ON/OFF)   • AIR COND, M     • HEADLAMPS - WIPER ACTIVATED   • AIR COND, M     • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS   • OUTSIDE TE     • ROOF CLEARANCE LIGHTS   • POWER LOC     • TOW HOOKS   • STEERING:TI					
EXTERIORINTERIOR• HEADLAMPS - AUTOLAMP (ON/OFF)• 4.2" PRODUC • AIR COND, M• HEADLAMPS - WIPER ACTIVATED• 4.2" PRODUC • AIR COND, M• MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS• OUTSIDE TE • PARTICULAT • POWER LOC 	50 DRW 4X4 CREW CHAS WB CHASSIS CAB WER STROKE V8 DIESEL ED AUTO TORQSHIFT	EXTERIOR OXFORD WH INTERIOR MEDIUM DA	RE D70:	393	California Air Resources Board Environment
JACK 40 GAL AFT OF AXLE FUEL TNK 350 AMP ALTERNATOR DUAL BATTERY CLOTH 40/20/40 SEAT	ICTIVITY SCREEN MANUAL FRONT YL FLOOR COVERING EMP DISPLAY TE AIR FILTER CKS AND WINDOWS FILT/TELESCOPE, UDIO CONTROLS	BASE PRIC TOTAL OP TOTAL VEH	AIRBAGS - SAFETY C. BELT-MINDER CHIME DRIVER/PASSENGER SECURILOCK® ANTI- SOS POST-CRASH AL WARRANTY 3YR/36,000 BUMPER 5YR/60,000 POWERTH 5YR/60,000 ROADSIDI 5YR/100,000 DIESEL E	ANOPY® E AIR BAGS THEFT SYS LERT SYS™ / BUMPER RAIN E ASSIST	These ratings are not directly comparable to For information on how to compara Protect the environment. Cho Greenhouse Gas Rating (tailpipe only C- Cleaner Vehicle emissions are a primary contributor to clima California Air Resources Board based on this vehicle
	ITEM #:	RAIL	Whether you decide to lease vehicle, you'll find the choice it for you. See your dealer for d	s that are right	IFD8W3HTORED70393     WARNING: Operating, servicing and maintaining a passed vehicle can expose you to chemicals including engine exh lead, which are known to the State of California to cause cancer at the state of Califor
li S	This label is affixed pursuant to the Fe Information Disclosure Act. Gasoline, State and Local taxes are not included options or accessories are not includ	License, and Title Fees, I. Dealer installed RC281 I	N RB 2X 425 001472 03 2		lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the er vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger-

