RE D71989

Whether you decide to lease or finance your

vehicle, you'll find the choices that are right

Ford Credit for you. See your dealer for details or visit

SPECIAL ORDER

www.ford.com/finance.

RD241 N RB 2X 425 001402 04 24 24

VEHICLE DESCRIPTION **SUPER DUTY**

2024 F450 4X4 SUPER CHASSIS XL 168" WB CHASSIS CAB 7.3L DEVCT NA PFI V8 ENGINE **10-SPEED AUTO TORQSHIFT**

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE


ford.com

STANDARD EQUIPMENT INCLUDED A	I NO EXTRA CHARGE			
EXTERIOR • HEADLAMPS - AUTOLAMP (ON/OFF) • HEADLAMPS - WIPER ACTIVATED • MIRRORS - HTD, PWR GLASS/ MANUAL-FOLD/TURN SIGNALS • ROOF CLEARANCE LIGHTS • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER SWAY CONTROL • TRAILER TOW WIRE HARNESS • WIPERS- INTERMITTENT	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • BLACK VINYL FLOOR COVERING • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS • UPFITTER SWITCHES	 FUNCTIONAL 4-WHEEL ANTILOCK BRAKE SYS FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST JEWEL EFFECT HEADLAMPS REMOTE KEYLESS ENTRY STABILIZER BAR, FRONT/REAR SYNC®4 W/8" SCREEN 	 SAFETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGS SECURILOCK® ANTI-THEFT SYS SOS POST-CRASH ALERT SYS™ MMERANTY SYR/36,000 BUMPER / BUMPER SYR/60,000 POWERTRAIN SYR/60,000 DIESEL ENGINE 	
INCLUDED ON THIS VEHICLE DTIONAL EQUIPMENT OF THE AUXILIARY AND	(MSRP) 660.00 NO CHARGE NO CHARGE 445.00 NO CHARGE 250.00 NO CHARGE NO CHARGE NO CHARGE 175.00 210.00		NS/OTHER \$58,035.00 1,740.00 1,740.00 LE & OPTIONS/OTHER 59,775.00	Exact a personalized estimates and compare vehicles
	RAMP ONE RC73	TOTAL	MSRP \$61,770.00	

EXTERIOR ORANGE INTERIOR

MEDIUM DARK SLATE VINYL

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



ITEM #


This label is affixed pursuant to the Federal Automobile

BAMP TWO

RAIL

41-0011 O/T 5C

(Ford)



1FD9X4HN4 RED71989 NB BU09

rates may apply. Text HELP for help



www.ford.com/help/privacy-terms/