KTP-000236 _{TX}	23X 905 6B 2 X LABL ADJ COV PRO	CS B10 RAMP BUMP	REC10641 SUPER	MAIL	022315 398/540
	CLE DESCRIPTION SUPPER DUC A024 F550 4X4 REG CHASS X 169" WB CHASSIS CAB 6.7 L POWER STROKE V8 D 10-SPEED AUTO TOROSHIP DOMESTROKE V8 0-SPEED AUTO TOROSHIP DOMESTROKE V8 DOMESTROKE V8 DOMESTR	SIS EXTERIOR OXFORD WH IESEL INTERIOR	RE C1064 TTE RK SLATE VINYL SAFETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - SAFETY CANOPY® BELT-MINDER CHIME DRIVER/PASSENGER AIR BAGA SECURILOCK® ANTI-THEFT SY SOS POST-CRASH ALERT SYS WARAGION BUMPER / BUMPE SYR/36,000 BUMPER / BUMPE SYR/36,000 BUMPER / BUMPE SYR/36,000 POWERTRAIN SYR/36,000 ROADSIDE ASSIST SYR/100,000 DIESEL ENGINE	S YS R	Conomy and Environ
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.660A 6.7 L POWER STROKE V8 DIESEL 10-SPEED AUTO TORQSHIFT 4.30 RATIO LIMITED SLIP AXLE PAYLOAD PLUS PACKAGE UPGRADE FRONT LICENSE PLATE BRACKET 1950# GVWR PACKAGE ENGINE BLOCK HEATER 50 STATE EMISSIONS SPARE TIRE AND WHEEL DELETE HIGH CAPACITY TRAILER TOW PKG JACK 40 GAL AFT OF AXLE FUEL TNK EXTRA HEAVY SERVICE SUSPENSION DUAL BATTERY REAR VIEW CAMERA & PREP KIT	(MSRP) 9,995.00 NO CHARGE 395.00 1,155.00 NO CHARGE 100.00 NO CHARGE 2 85.00 580.00 580.00 580.00 55.00 NO CHARGE 125.00 NO CHARGE 125.00 NO CHARGE 415.00	TOTAL VEH	DRMATION Sons/OTHER \$56,9 12,7 CLE & OPTIONS/OTHER 69,6	ASRP) 920.00 735.00 995.00 Calculate personalized e	DIDUCTION STATES AND COMPARE VEHICLES
	This label is affixed pursua Information Disclosure Act. State and Local taxes are n	RAIL Ford EM #: 23-7953 O/T 59 Ford Credit Int to the Federal Automobile Gasoline, License, and Title Fees, State	MSRP \$71,650.0 Whether you decide to lease or finance vehicle, you'll find the choices that are t for you. See your dealer for details or v www.ford.com/finance. SPECIAL ORDER 6B 2X 420 000236 03 04 24	e your e right visit WARNING: Operative vehicle can expose lead, which are known to t	1FDUF5HT2REC10641 ing, servicing and maintaining a passenger vehic you to chemicals including engine exhaust, carb he State of California to cause cancer and birth c bid breathing exhaust, do not idle the engine exca area and wear gloves or wash your hands frequ o www.P65Warnings.ca.gov/passenger-vehicle.

05/20/2024

022315 398/540



1FDUF5HT2 REC10641 NB BU09

cancer and birth defects or other reproductive harm. le the engine except as necessary, service your your hands frequently when servicing your vehicle.

apply. Text HELP for help



www.ford.com/help/privacy-terms/