KAN-000687 _{KS}	53C 911 6B 2 X LABL ADJ COV PRCS	B10 RAMP BUMP	1FDVU4X87PKB17064	TRANSIT	MAIL	0 30
Ford.com	ICLE DESCRIPTION TRANSIT 2023 350 HD HR PASS XL RW XL TRIM 3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSION	O INTE	PK B ERIOR XFORD WHITE RIOR ARK PALAZZO GRAY VINYL	17064		vironmer
STANDARD EQUIPMENT INCLUDED A EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.301A 195/75R16C BSW ALL-SEASON 4.10 LIMITED SLIP AXLE FRONT LICENSE PLATE BRACKET 253 DEGREE OPENING AUTO START STOP REMOVAL WIFI 4G LTE HOTSPOT DELETE 10360# GVWR PACKAGE 2WAY DRV/PASS PALAZZO VINYL 50 STATE EMISSIONS BUILDERS PREP PACKAGE .VINYL FRONT FLOOR COVERING .MODIFIED VEHICLE WIRING SYS .LESS REAR SEAT PACK DUAL BATTERIES (70 AMP-HR) FRONT OVERHEAD SHELF DAYTIME RUNNING LAMPS E-85 FLEX FUEL CAPABLE	AT NO EXTRA CHARGE PURE PURE PURE PURE PURE PURE PURE PURE	EUNCTIONAL AUTO HIGH-BEAM H ELECTRONIC PWR A FORDPASS™ CONNI HOTSPOT TELEMATI FORWARD COLLISIO HILL START ASSIST ANE-KEEPING SYS POST-COLLISION BE PRE-COLLISION ASS REAR VIEW CAMERA W/ TRAILER HITCH A SELECTABLE DRIVE USB PORTS - 5 AMP	SST STEER ECT 4GWI-FI CS MODEM N WARNING FEM AKING SST V/AEB SSIST MODES • ADVANCET • AIRBAGS ⊠ SAFETY CAI • BRAKES - 4 • SECURILOC • SOS POST- • SOS POST- • SIST • 3YR/36,000	FETY BELTS RAC [™] WITH RSC® FRONT, SIDE AND NOPY® SYSTEM WHEEL DISC W/ABS CRASH ALERT SYS [™] SURE MONIT SYS BUMPER / BUMPER POWERTRAIN ROADSIDE ASSIST (MSRP) \$54,270.00 - 820.00	For inform Protect the	
	RAMP ONE CS15 RAMP TWO ITEM 1 This label is affixed pursuant to Information Disclosure Act. Gastate and Local taxes are not in options or accessories are not in options options or accessories are not in options op	53-5306 O/T 59 to the Federal Automobile asoline, License, and Title Fees, included. Dealer installed	Whether you decid		WARNING: Operating, s vehicle can expose you lead, which are known to the S To minimize exposure, avoid br vehicle in a well-ventilated area For more information go to www	servicing and maintaining a part to chemicals including engine tate of California to cause can

05/10/2024

