OHI-000148 IL 53	W 705 6B 2 X LABL ADJ COV PRCS	B10 RAMP BUMP	DWE3FN0SDD01567	E-SERIES	MAIL	0 45
	E DESCRIPTION -SERIES 2025 E-350 CUTAWAY DRW DRW 138 WB 7.3L V8 PREMIUM-RATED EN ELEC 6-SPD AOD W/TOW-HA	G. INTERI	IOR FORD WHITE	01567		onomy and En
LT225/75R16E DRW HANKOOK 4.10 LIMITED SLIP AXLE XE2 HIGH-SERIES EXT UPGRADE PKG POWER EQUIPMENT GROUP REAR VIEW CAMERA W/MIRROR RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 11500# GVWR PACKAGE 50 STATE EMISSIONS USER DEFINED SWITCHES CRUISE CONTROL TRAILER TOWING PKG CLASS I MIRRORS, MAN TLR TOW W/PWR GLS FRAME PUCKS (ISOLATORS) CLOTH BUCKET SEATS DAYTIME RUNNING LIGHTS	O EXTRA CHARGE AIR CONDITIONING AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING GLOVE BOX WITH POWERPOINT POWERPOINT - 12V (FRONT) STEERING - TILT/TELESCOPIC TACHOMETER VINYL FRONT HEADLINER VINYL SUN VISORS (MSRP) NO CHARGE 270.00 100.00 600.00 495.00 NO CHARGE NO CHARGE NO CHARGE NO CHARGE 85.00 240.00 135.00 230.00 50.00 NO CHARGE 85.00 240.00 135.00 230.00 50.00 NO CHARGE 25.00 NO CHARGE	Ē	• 3 POINT S DDEM • 4-WHEEL BRAKING DENT • DRIVER/F • ELECTRO • TRACTIO WARRANT • 3YR/36,00 • 5YR/60,00	SAFETY BELTS ANTI-LOCK DISC SYSTEM PASSENGER AIR BAGS DNIC STABILITY CNTRL N CONTROL TY 000 BUMPER / BUMPER 000 POWERTRAIN 000 ROADSIDE ASSIST (MSRP) \$38,045.00 2,230.00 YOTHER 40,275.00 1,995.00 E USE. VOID IF	REG fueleconc Calculate personalized es	UIRED O
	RAMP ONE RA6K RAMP TWO	RAIL	<b>TOTAL MSRP</b> Whether you de vehicle, you'll fi	\$42,270.00 ecide to lease or finance your ind the choices that are right		1FDWE3FN0SDD01567
	This label is affixed pursuant of Information Disclosure Act. G State and Local taxes are not options or accessories are not	53-0327 O/T 59 F o the Federal Automobile asoline, License, and Title Fees, ncluded. Dealer installed	ord Credit for you. See you www.ford.com/ SPECIAL R889 R 6B 2X 515 00	ur dealer for details or visit /finance. ORDER	Vehicle can expose y lead. which are known to th	ng, servicing and maintaining a pass you to chemicals including engine e e State of California to cause cance d breathing exhaust, do not idle the area and wear gloves or wash your www.P65Warnings.ca.gov/passeng

05/20/2024

