KTP-002680 FL 4-REBILL,	NB,202680, PK272 11102	ULCUWFLCERTCERTCERTTRDRAMPBUMP	CAMPBOOKEXFLROTA 01 3094/
VEHICLE DESCRIPT EXAMPLE VEHICLE DESCRIPT Description EXTERION • EASY FUEL® CAPLESS FILLER • GRILLE-TWIN SPAR, CHROME • HEADLAMPS - WIPER ACTIVATED • HID VENU • HID VENU • POWER LIFTGATE • ROOF-RACK SIDE RAILS-BRGHT • RUNNING BOARD-PWR DEPLOY • TAILLAMPS/FOG LAMPS - LED • TRAILER SWAY CONTROL	INPERIOR OF THE PERSON STREET	CERT CERT CERT TRD RAMP BUMP RE ACT STAR WHITE MET TRI-COAT STAR WHITE MET TRI-COAT 'ERIOR JAVA DEL RIO LTH-TRM SEATS ERA 22 SPKR W PREP PAK TIRIAL) 0™ASSIST2.0 NECT 4GWI-FI TICS MODEM PENSION STL SCRN BRAKING SSIST LESS KEYPAD L- NA AK&HI A15.5" SCRN	AMP BOOK EXFL ROTA 3094/
			Frontal CrashDriver PassengerImage: CrashBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size arSide CrashFront seat Rear seatBased on the risk of injury in a side impact.Based on the risk of injury in a side impact.Rollover Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-42
	CF29	TOTAL MSRP \$83,845.00 Whether you decide to lease or finance your	1FMJU1N80REA15798
	RAMP TWO CONVOY ITEM #: 24-Z901 O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	Ford Credit for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the evehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

05/18/2024

