CHI-008041 _{CA}	9-NORMAL,NB,108041,RC121 221	8 120240320 2093	UTC U W CA CERT CERT TRD RAMP BUMP	CAMP BOOK EXFL ROTA 022468 1051/2260
Ford.com	CLE DESCRIPTION EXPLORER XLT RWD 2024 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION	INTERIOR	RG A56773 MET TRI-COAT /EX SEAT MTRL	Fuel Economy and Environ Fuel Economy MPG. The best vehicle r
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DOOR HANDLES - BODY COLOR • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • LED SIGNATURE LIGHTING • MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 202A • SEMOTE START SYSTEM • HEATED STEERING WHEEL • BOMTE START SYSTEM • HEATED STEERING WHEEL • WAY POWER PASSENGER SEAT DTIONAL EQUIPMENT/OTHER 2024 MODEL YEAR STAR WHITE MET TRI-COAT • 18" 5-SPOKE PAINTED ALUM WHLS • P255/65R18 A/S BSW TIRES • O STATE EMISSIONS 4G LTE WI-FI HOTSPOT CREDIT REAR AUXILIARY CNTRLS CREDIT FRONT LICENSE PLATE BRACKET	In the second se		\$38,670.00	Image: Angle Angl
	RAMP ONE			Rollover★ ★ ★ ★Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (★ ★ ★ ★), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-42361FMSK7DH9RGA56773
	ITEM #:	CONVOY 71-0487 O/T 2 Ford Credit	MSRP \$44,480.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	
	This label is affixed pursuant to the Information Disclosure Act. Gasol State and Local taxes are not inclu options or accessories are not inclu	e Federal Automobile line, License, and Title Fees, Ided. Dealer installed RC121 N	RB 2X 425 008041 03 12 24	lead, which are known to the State of California to cause cancer and birth d To minimize exposure, avoid breathing exhaust, do not idle the engine exce vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202403202093

05/16/2024

