CHI-003893 MD 9-NORMAL	,NB,103893,RA241 <b>658</b>		UTC U W MD CERT CERT CERT TRD RAMP BUMP C	CAMP BOOK EXFL ROTA 021483 291/1687
2024 119" 2.3L ford.com	LORER EXPLORER XLT 4WD WHEELBASE ECOBOOST I-4 ENGINE PEED AUTO TRANSMISSION	EXTERIOR AGATE BLACK INTERIOR EBONY/LT SLA	RG A17637 METALLIC TE ACTIVEX SEAT	EPA DOT Fuel Economy and Environ Fuel Economy R 2 2 MPG Standard SUVs range fro MPG. The best vehicle r
EASY FUEL® CAPLESS FILLER SRD RO HEADLAMPS - AUTO LED LED SIGNATURE LIGHTING MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS LTHR W POWER LIFTGATE W/MOUN PRIVACY GLASS - REAR DOORS REAR INT WIPER/WASH/DFRST POWER REAR SPOILER, BODY COLOR ROTARY ROOF-RACK SIDE RAILS-BLACK SRD RO	Image: Second state sta	DESTINATION & TOTAL BEFO 4WD REGIOI TOTAL SAVI RESIDENCY TO DISCOUT ON CUSTO	\$40,670.00       IS/OTHER     \$40,670.00       IS/OTHER     \$750.00       E & OPTIONS/OTHER     49,420.00       & DELIVERY     1,595.00       DRE DISCOUNTS     51,015.00       NAL DISCOUNT     - 300.00	Image: State Stat
				Rollover★ ★ ★ ★Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (★ ★ ★ ★), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-4236
	RAMP ONE     CD06       RAMP TWO     CONV       ITEM #:     27-6229 (CONV)	от 2 Ford Credit <sup>fc</sup>	MSRP \$50,715.00 /hether you decide to lease or finance your ehicle, you'll find the choices that are right or you. See your dealer for details or visit ww.ford.com/finance.	IFMSK8DH7RGA17637     WARNING: Operating, servicing and maintaining a passenger vehicl vehicle can expose you to chemicals including engine exhaust, carbor lead, which are known to the State of California to cause cancer and birth d
	This label is affixed pursuant to the Federal A Information Disclosure Act. Gasoline, Licens State and Local taxes are not included. Deale options or accessories are not included unles	se, and Title Fees, er installed RA241 N R	B 2X 425 003893 01 24 24	To minimize exposure, avoid breathing exhaust, do not idle the engine excerned vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

