СНІ-001996 т	X 9-NORMAL,NB,101996,SC261 34	120250404 6819 BLEND 6819	UTC U W TX CERT CERT CERT TRD RAMP BUMP C	CAMPBOOKEXFLROTA 02
Ford.com	VEHICLE DESCRIPTION EXPLORER ACTIVE RWI 2025 EXPLORER ACTIVE RWI 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISS	SPACE WHIT	SG CO2842 E METALLIC E GRAY CLOTH SEATS	EPA DOT Fuel Economy and Env Fuel Economy MPG. The be
STANDARD EQUIPMENT INCLUE EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • MIRRORS-MAN-FOLD DUAL PW HEATED WITH APPROACH LAMF • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS • VARIABLE INTERVAL WIPERS • OPTIONAL EQUIPMENT/OTHER • 18" SILVER PAINTED ALUM WHLS • P255/65R18 A/S BSW TIRES 50 STATE EMISSIONS MINI SPARE AND JACK KIT FRONT LICENSE PLATE BRACKET	INTERIOR 12.3" LCD DIGITAL CLUSTER 1TOUCH UP/DOWN DR/PASS WIN 3RD ROW - 50/50 FOLD FLAT 3RD ROW - 50/50 FOLD FLAT DUAL ILLUM VIS VANITY MIRR FRONT ROW HEATED SEATS POWER DRIVER'S SEAT POWER PASS SEAT POWERPOINTS - 12V ROTARY GEAR SHIFT DIAL TILT/TELESCOPING STEERING W/WHEEL MOUNTED CONTROLS USB-C - ALL ROWS (MSRP)		 AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® INDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM™ SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST CMMATION \$39,785.00 	Image: Additional state of the state of
	RAMP ONE CH7L RAMP TWO	CONVOY	MSRP \$41,780.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not in options or accessories are no	asoline, License, and Title Fees, ncluded. Dealer installed SC261 N	RB 2X 555 001996 03 26 25	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

