KIP-004530 TX 9-NORMAL, NB, 204530, RB082 11419			CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA 4144/4	
	ICLE DESCRIPTION SUPER DUTY 2024 F350 SRW 4X2 CREW CAB XL 176" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-G	EXTERIOR OXFORD WHIT INTERIOR	RE D33932 Te K SLATE VINYL	California Air Resources Board Environment These ratings are not directly comparable to
EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE DYNOME EQUIPMENT PKG.610A 10-SPEED AUTO TOROSHIFT-G 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET 1060# GYWR PACKAGE 50 AMP ALTERNATOR XL DRIVER ASSIST PACKAGE XL ORIVER ASSIST PACKAGE FOG LAMPS	INTERIOR 4.2" PRODUCTIVITY SCREEN 4.1R COND, MANUAL FRONT CLOTH SUN VISORS DRIVER SEAT-MANUAL LUMBAR OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING: TILT/TELESCOPE, CRUISE & AUDIO CONTROLS (MSRP) NO CHARGE NO CHARGE NO CHARGE 85.00 730.00 225.00	 EUNCTIONAL 4-WHEEL ANTILOCK BRAKE SYS FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST REAR VIEW CAMERA REAR VIEW CAMERA SYNC®4 W/8" SCREEN TWIN I-BEAM INDEPENDENT FRT SUSPENSION W/STAB BAR 	\$50,015.00 NS/OTHER 1,040.00 LE & OPTIONS/OTHER 51,055.00	
	RAMP ONE RK34	RAIL	MSRP \$53,050.00 Whether you decide to lease or finance your	1FT8W3AAXRED33932
	RAMP TWO ITEM #: 5. This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not includ options or accessories are not included options optins options options optins options options optins options options	2-F000 O/T 2 Ford Credit Ford Credit Ford Credit Ford Credit BB082 N I	vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RB 2X 425 004530 02 08 24	WARNING: Operating, servicing and maintaining a passen vehicle can expose you to chemicals including engine exha lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the en vehicle in a well-ventilated area and wear gloves or wash your har For more information go to www.P65Warnings.ca.gov/passenger-v

