KTP-000538 99	48B 027 7B X X LABL ADJ COV PRCS	B10 RAMP BUMP	1FTBF2AAXPED4	974	SUPER	MAIL		01 180
	ICLE DESCRIPTION			E D4	0974	California	Air Resourc	es Boarc
ford.com	2023 F250 SRW 4X2 REG CA XL 142" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGIN 10-SPEED AUTO TORQSHIFT	- IE INT	TERIOR OXFORD WHITE TERIOR MEDIUM DARK SL				Enviro	nmen
STANDARD EQUIPMENT INCLUDED	AT NO EXTRA CHARGE						ngs are not directly For information on I	
EXTERIOR • BOX RAIL/TAILGATE MOLDINGS • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • PICKUP BOX TIE DOWN HOOKS • POWER TAILGATE LOCK • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • WIPERS- INTERMITTENT	INTERIOR • 4.2" PRODUCTIVITY SCREEN • AIR COND, MANUAL FRONT • CLOTH SUN VISORS • DRIVER SEAT-MANUAL LUMBAR • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS	EUNCTIONAL • 4-WHEEL ANTILOC • FORDPASS™ CON HOTSPOT TELEMA • HILL START ASSIS • REAR VIEW CAMER • REMOTE KEYLESS • SYNC®4 W/8" SCR • TWIN I-BEAM INDE FRT SUSPENSION	CK BRAKE SYS INECT 5GWI-FI ATICS MODEM BT RA S ENTRY REEN EPENDENT W/STAB BAR	AIRBAGS - SAFI BELT-MINDER (DRIVER/PASSEI SECURILOCK® SOS POST-CRA ARRANTY BYR/36,000 BUN SYR/100,000 DIE SYR/60,000 POV	™ WITH RSC® ETY CANOPY® CHIME NGER AIR BAGS ANTI-THEFT SYS SH ALERT SYS™ MPER / BUMPER ESEL ENGINE	Prote	ect the enviror use Gas Ratin	nment. Ch
INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.600A 10-SPEED AUTO TORQSHIFT-G 3.73 ELECTRONIC-LOCKING AXLE 10000# GVWR PACKAGE 50 STATE EMISSIONS ROOF CLEARANCE LIGHTS JACK 250 AMP ALTERNATOR	NO CHARGE BASE PRICE \$43				(MSRP) \$43,970.00 610.00		ns are a primary cont sources Board based	
	430.00 NO CHARGE 95.00 85.00 85.00 1,895.00 1,895.00 1,895.00 1,895.00 1,895.00 1,895.00 1,895.00 1,895.00 1,895.00							
						Frontal Crash Based on the risk Should ONLY be o	Driver Passenger of injury in a frontal impac compared to other vehicles	Not Rate Not Rate ot. s of similar size and
						Side Crash Based on the risk	Front seat Rear seat of injury in a side impact.	Not Rate Not Rate
						Rollover Based on the risk	of rollover in a single-vehi	Not Rate
						Star ratings rang	je from 1 to 5 stars (★ onal Highway Traffic www.safercar.gov o	$\star \star \star \star \star$), with Safety Administ
	RAMP ONE CM1K		TOTAL MS		6,475.00		1FTBF2AA)	(PED40974
	RAMP TWO	RAIL #: 48-7500 O/T 2	Ford Credit for yo	e vou'll find the) lease or finance your choices that are right er for details or visit e.	WARNING: vehicle can e	Operating, servicing and rr expose you to chemicals in wn to the State of Californ	aintaining a passe cluding engine ext ia to cause cancer
	State and Local taxes are not i	asoline, License, and Title Fees,	B418 A 7BX X	340 000538	07 18 23	To minimize exposu vehicle in a well-ver	re, avoid breathing exhaus tilated area and wear glov n go to www.P65Warnings	st, do not idle the e ves or wash your ha

05/09/2024

