
KAN-002678 FL	9-NORMAL, NB, 202678, PE052	3443 120230513 BLEND		_ · · ·		AMPBOOKEXFLROTA	112
	FRANSIT		PK	B075	572	California Air I	Resources Board
ford.com	2023 250 LR CARGO RWI 130" WHEELBASE 3.5L PFDI V6 (GAS) 10-SPEED TRANSMISSIO	O INTE	ERIOR XFORD WHITE RIOR BONY CLOTH			Er	nvironmen
STANDARD EQUIPMENT <u>INCLUDED AT</u>	NO EXTRA CHARGE					Ū.	not directly comparable rmation on how to comp
EXTERIOR • AUXILIARY FUEL PORT • BODY SIDE MOLDINGS - BLACK • BUMPERS - CARBON BLACK • FULL SIZE SPARE TIRE/WHEEL • HEADLAMP COURTESY DELAY	INTERIOR • AIR CONDITIONING • ASSIST HANDLE - B-PILLAR • ASSIST HANDLES - A-PILLAR • CENTER CONSOLE • INTERIOR LIGHTING - LED	FUNCTIONAL • AUTO HIGH-BEAM H • ELECTRONIC PWR A • FORWARD COLLISIC • HILL START ASSIST • LANE-KEEPING SYS [•]	EADLAMPS • 3 PC SST STEER • ADV N WARNING • AIRI SAF	ETY/SECURITY DINT SAFETY BELT ANCETRAC [™] WITI BAGS ⊠ FRONT, SIE ETY CANOPY® SYS	H RSC® DE AND STEM	Protect the	e environment. Ch
• WIPERS - RAIN-SENSING	• INTERIOR EIGHTING - LED • LOCKING GLOVE BOX • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER	POST-COLLISION BF PRE-COLLISION ASS REAR VIEW CAMERA W/ TRAILER HITCH A SELECTABLE DRIVE	RAKING • SEC SIST W/AEB • SOS • TIRE SSIST	 BRAKES - 4WHEEL DISC W/ABS SECURILOCK® ANTI-THEFT SYS SOS POST-CRASH ALERT SYS™ TIRE PRESSURE MONIT SYS 	Greenhouse G	as Rating (tailpipe or C	
		• SIDE-WIND STABILIZ	ATION • 3YR • 5YR	/36,000 BUMPER / /60,000 POWERTR /60,000 ROADSIDE	AIN	Cleaner	Using alternative
INCLUDED ON THIS VEHICLE	(MSRP)				(MSRP)		primary contributor to clim Board based on this vehicl
OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.101A 3.73 NON-LIMITED SLIP AXLE					\$45,405.00 1,563.00		
FRONT LICENSE PLATE BRACKET FIXED REAR AND PASS DOOR GLASS TIE DOWN CARGO HOOKS EXTERIOR UPGRADE PKG - SRW .FRONT FOG LAMPS .SRW - STEEL W/ SILVER COVER .WIPER ACTIVATED HEADLAMPS	425.00 25.00 535.00				46,968.00 1,895.00	Overall Vehicle So	ENT 5-STAR SAFETY core Not Rat ngs of frontal, side and rollover. to other vehicles of similar size ar
AUTO START STOP REMOVAL WIFI 4G LTE HOTSPOT DELETE 9070# GVWR PACKAGE 2WAY DRV/PASS EBONY CLOTH SHIP-THRU NATIONAL FLEET SVCS 50 STATE EMISSIONS RADIO - SYNC3, 4" SCN	- 50.00 - 20.00 NO CHARGE 115.00 NO CHARGE NO CHARGE 280.00					Frontal Driv Crash Pas	
CRUISE CONTROL BLACK HALOGEN HEADLAMPS 2 ADDITIONAL KEYS DAYTIME RUNNING LAMPS E-85 FLEX FUEL CAPABLE SPECIAL ORDER 71 2339	325.00 - 455.00 75.00 45.00 NO CHARGE					Side Fro	nt seat Not Rat ar seat Not Rat
VSO ID CODE TRANSIT NA 023 DEACT TELEM MODEM 023 TRNS ODO NONTAMP 023 TRANSIT DEL RKR MLDGS 023 TRANSIT	N/C 32.00 141.00 N/C					Rollover Based on the risk of rollover	
SCUFF PLATES 023 TRANSIT	90.00					Source: National Hig	l to 5 stars (★ ★ ★ ★ ★), wit hway Traffic Safety Adminis safercar.gov or 1-888-327-42
	RAMP ONE CC15		TOTAL MSR	P \$48,8	63.00		1FTBR1Y81PKB07572
	RAMP TWO	CONVOY	(Jord) vehicle vo	ou decide to lease o ou'll find the choices	that are right	WARNING: Operating,	servicing and maintaining a pass-
	CA21	71-A783 O/T LM uant to the Federal Automobile	Ford Credit for you. Se www.ford	e your dealer for de .com/finance.	tails or visit	lead, which are known to the S	servicing and maintaining a passe u to chemicals including engine ex State of California to cause cancer preathing exhaust do not idle the
	Information Disclosure A	Act. Gasoline, License, and Title Fees, e not included. Dealer installed	SPECI	AL ORDEF	2	vehicle in a well-ventilated are	preathing exhaust, do not idle the e a and wear gloves or wash your h ww.P65Warnings.ca.gov/passenge

1202305134169



vith 5 being the highest. nistration (NHTSA). 236



ssenger vehicle, pickup truck, v exhaust, carbon monoxide, phtl cer and birth defects or other reproductive narm. e engine except as necessary, service your r hands frequently when servicing your vehicle. ger-vehicle

rates may apply. Text HELP for help

sending vehicle data (e.g., diagnostics) to Ford. See

in-vehicle Settings for connectivity options.



www.ford.com/help/privacy-terms/