				IPBOOKEXFЦROTABATTI 1462,
Ford	CLE DESCRIPTION RANGER 2025 SUPERCREW 4X4 XLT 128" WHEELBASE 2.3L ECOBOOST ENGINE 10-SPEED AUTO TRANSMISSIO	EXTERIOR OXFORD WHIT INTERIOR ON EBONY CLOTH		EPA DOT Fuel Economy and Env Fuel Economy Standard Pic 87 MPG Th
ford.com	10-SPEED AUTO TRANSMISSIC		SEATS	NIFG 87 MPG. Th MPGe.
EXTERIOR • DAYTIME RUNNING LAMPS • EASY FUEL® CAPLESS FILLER • FENDER BADGE • FOG LAMPS • FULL SIZE SPARE TIRE/WHEEL • FULLY BOXED STEEL FRAME • HEADLAMPS - AUTO HIGH BEAM • LED REFLECTOR HEADLAMPS • PRIVACY GLASS • REMOTE TAILGATE LOCK • TAILLAMPS-LED • WHEEL LIP MOLDINGS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 301A • UNEEL LIP MOLDINGS NUMER SLIDING REAR WINDOW • DUAL-ZONE ELEC CLIMATE CONTRO OPTIONAL EQUIPMENT/OTHER 255/65R 18 A/T TIRE 3.73 LOCKING RR DIFFERENTIAL 4X4 REGIONAL DISCOUNT PKG BLACK APPEARANCE PACKAGE 1.8" BLACK PAINTED ALUM WHEEL BLACK GRILLE FRONT LICENSE PLATE BRACKET RUNNING BOARDS - BLACK TRAILER TOW PACKAGE	Internet Subsection of the series of the se	DESTINATION TOTAL BEF	\$39,595.00 NS/OTHER 3,605.00 LE & OPTIONS/OTHER 43,200.00 & DELIVERY 1,595.00 ORE DISCOUNTS 44,795.00 NAL DISCOUNT P - 250.00 -	Image: A generation of the second state state of the second state of the second state of the se
	RAMP ONE RH4F RAMP TWO ITEM #: This label is affixed pursuant to	21-402Y O/T 2	MSRP \$44,545.00 Whether you decide to lease or finance your ehicle, you'll find the choices that are right or you. See your dealer for details or visit www.ford.com/finance.	Rollover ★ ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★ ★), with Source: National Highway Traffic Safety Administry www.safercar.gov or 1-888-327-42 IFTER4HH7SLE18957 WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine explead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the
	Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	cluded. Dealer installed SD221 N F	B 2X 520 009384 04 22 25	vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

