
FD

9-NORMAL, NB, 105089, SE141 7969

ULC U W MO 220250523 1468 CERTCERT TRD RAMPBUMPCAMPBOOKEXFLROTABATT

	DESCRIPTION -150 RAPTO 2025 RAPTOR 4X4 SUPERCREW 145" WHEELBASE 3.5L ECOBOOST HIGH OUTPUT ELEC TEN-SPEED AUTO TRANS	EXTERIOR AGATE B INTERIOR	SF B28709 BLACK METALLIC BLACK SEAT	EPA DOT Fuel Economy and E   Fuel Economy Standard   Fuel Economy MPG   MPGe. Standard
EXTERIOR • 5 LINK REAR SUSPENSION • BUMPER - RAPTOR-UNIQUE FRONT PERFORMANCE • DUAL EXHAUST SYSTEM W/DUAL TAILPIPES • FUEL TANK - 36.0 GALLON • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTO LAMP (ON/OFF) • LED PROJECTOR W/ DYNAMIC BENDING HEADLAMPS • LED SIDE-MIRROR SPOTLIGHTS • RIGID® LED FOG LAMP • WHEEL LIP MOLDINGS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 302A • RAPTOR SERIES • 17" CAST ALUM BEAD-LOCK CAPAB • DUAL VALVE SHOCKS OPTIONAL EQUIPMENT/OTHER .37 X 12.5R17 BSW ALL-TERRAIN 4.10 ELECTRONIC LOCK RR AXLE M 7400# GVWR PACKAGE FRONT LICENSE PLATE BRACKET M	INTERIOR 12" PRODUCTIVITY SCREEN 2 ND ROW HEATED SEATS 4 AC W/DUAL CLIMATE CONTROL 2 OMPASS 2 HEAD-UP DISPLAY HEAD-UP DISPLAY HTD LTHR WRAPPED STR WHL 1 TD DYENTILATED FRT SEATS 0 UTSIDE TEMP DISPLAY PEDALS-PWR ADJ W/MEMORY POWER LOCKS AND WINDOWS RAPTOR BRANDED FLOOR MATS 2 RAPTOR-UNIQUE CENTER STACK 3 TEERING - TILT/TELESCOPIC WHEEL WITH AUDIO 11,470.00 NO CHARGE NO CHARGE 1,495.00	BASE F TOTAL TOTAL	EM • PERIMETER ALARM • SECURE PKG 1 YR INCLUDED • SOS POST-CRASH ALERT SYS™ • TIRE PRESSURE MONIT SYS • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST TEM (MSRP)	fueleconomy.gov Calculate personalized estimates and compare vehicles
	CA6P		FAL MSRP \$93,965.00   Whether you decide to lease or finance your	1FTFW1RG6SFB28709
	ITEM #:	3-P862 O/T 2 Federal Automobile ne, License, and Title Fees, led. Dealer installed	vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe



2202505231468