220240412 3377 BLEND 3377

FORD PERFORMANCE 2024 F 3.5L E	<b>O RAPTOR</b> APTOR 4X4 SUPERCREW HEELBASE COBOOST HIGH OUTPUT	EXTERIOR ANTIMATTER B INTERIOR		EPA DOT Fuel Economy and En Fuel Economy
ELEC TEN-SPEED AUTO TRANS       BLACK LEATHER BUCKET SEATS         STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE       Included at no extra charge				<b>16 14 18</b>
BUMPER - RAPTOR-UNIQUE     FRONT PERFORMANCE     DUAL EXHAUST SYSTEM W/DUAL     TAILPIPES     FUEL TANK - 36.0 GALLON     HEADLAMPS - AUTO HIGH BEAM     HEADLAMPS - AUTOLAMP     (ON/OFF)     LED PROJECTOR W/ DYNAMIC     BENDING HEADLAMPS     LED SIDE-MIRROR SPOTLIGHTS     PAPTOR	UCTIVITY SCREEN • 360 HEATED SEATS • B&C AL CLIMATE CONTROL • BEL CRUISE CONTROL • FOR MADJELAY • FOD WRAPPED STR WHL • MO TEMP DISPLAY • PRC OCKS AND WINDOWS • REV BRANDED FLOOR MATS REA JNIQUE CENTER STACK • SKI A - TILT/TELESCOPIC • SYN ITH AUDIO • TEF • TRA	CTIONAL D-DEGREE CAMERA O UNILEASHED, 14 SPKR D UTILITY PKG RDPASS™ CONNECT 5GWI-FI TSPOT TELEMATICS MODEM X LIVE VALVE SHOCKS DBILE OFFICE PKG O TRAILER BACKUP ASSIST O TRAILER HITCH ASSIST VERSE SENSING AND AR VIEW CAMERA ID PLATES NC®4 W/EVR & 12" SCREEN RRAIN MANAGEMENT SYSTEM AL CONTROL PRICE INFORM BASE PRICE TOTAL OPTION TOTAL VEHICLE DESTINATION 8	\$78,330.00 S/OTHER 2,090.00 E & OPTIONS/OTHER 80,420.00	combined city/hwy       city       highway         6.2       gallons per 100 miles         Annual fuel       COSA         \$\$3,3,40,000       Image: Single and costs single and
	RAMP ONE	TOTAL	MSRP \$82,415.00	1FTFW1RG9RFA78818
	RAMP TWO RAMP TWO RAMP TWO This label is affixed pursuant to the Federal Information Disclosure Act. Gasoline, Licer State and Local taxes are not included. Dea options or accessories are not included un	2 O/T 2 I Automobile nse, and Title Fees, aler installed BD021 N B	Yhether you decide to lease or finance your ehicle, you'll find the choices that are right or you. See your dealer for details or visit ww.ford.com/finance. B 2X 435 002906 04 02 24	WARNING: Operating, servicing and maintaining a particular which are known to the State of California to cause canon to minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen
				22024041

