U | W | IL | UTC CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA

5-PA: TWIN		G INTERIO		526	EPA DOT Fuel Economy and En Fuel Economy MPG Small SU The best
EASY FUEL® CAPLESS FILLER EXHAUST TIPS - STAINLESS STEEL FOG LAMPS-LED GRILLE - CHROME HEADLAMPS - AUTO HIGH BEAM HEADLAMPS - WIPER ACTIVATED HEADLAMPS - LED WITH SIGN LTG W/DARK BEZEL W/CRUIN LIFTGATE - HANDS-FREE HTD, 10 MIRRORS - PWR/HTD/MAN FOLD & 6-WAY LED SIG/APPROACH LAMP/MEM POWER	W AC POWER OUTLET UP/DOWN DR/PASS WIN SYFOLD REAR BENCH FLIGHTING M REARVIEW MIRROR UM VIS VANITY MIRR DNE ELECTRONIC IMATE CONTROL R WRAPPED STR WHL E AND AUDIO CTRLS WAY PWR DRV W/MEM PWR PASS POINTS - 12V GEAR SHIFT DIAL	FUNCTIONAL • B&O SOUND SYSTEM, 12 • FORD CO-PILOT360™ • FORDPASS™ CONNECT 4 HOTSPOT TELEMATICS M • FORWARD SENSING SYS • INTELL ACCESS W/PUSH • REAR PARKING SENSORS • REAR VIEW CAMERA • REMOTE START SYSTEM • SIRIUSXM® W/360L- NA A • SYNC®4A W/EVR & 12" SO • UNIVER GARAGE DOOR C • WIRELESS CHARGING PA	 AIRBAG-DRIVER/PASS IGWI-FI AIRBAGS - DUAL STAC IODEM AIRBAGS - FRONT SEA TEM MOUNTED SIDE IMPAC START AIRBAGS - SAFETY CA S INDIV TIRE PRESS MO LATCH CHILD SAFETY PERIMETER ALARM AK&HI PERSONAL SAFETY SY CREEN SOS POST-CRASH ALE DPENER JD WARRANTY SYR/36,000 BUMPER / SYR/60,000 POWERTR 	S KNEE GE FRONT AT CT NOPY® NIT SYS SYSTEM YSTEM™ ERT SYS™ BUMPER AIN	 Letter State Lette
INCLUDED ON THIS VEHICLE (MSR EQUIPMENT GROUP 300A OPTIONAL EQUIPMENT/OTHER 245/50R20 A/S BSW TIRES FLR LINERS, FRT/RR W/CARPET 200.0 50 STATE EMISSIONS NO CHARG PANORAMIC VISTA ROOF 1,595.0 MINI SPARE WHL/TIRE 100.0 20" BRT MCH ALM WHL W/PTD PKT 995.0 FRONT LICENSE PLATE BRACKET NO CHARG	0 = 0 0	BA TO TO	• 5YR/60,000 ROADSIDE	ASSIST (MSRP) \$43,720.00 2,890.00 46,610.00 1,495.00	Actual results will vary for many reasons, including driving of vehicle. The average new vehicle gets 28 MPG and costs \$9, based on 15,000 miles per year at \$3.60 per gallon. MPGe is emissions are a significant cause of climate change and smother significant cause of climate significant cause of similar size of similar size significant cause of similar size significant cause of the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size significant cause of the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (*****), Source: National Highway Traffic Safety Admited significant cause of
	RAMP ONE RC73 RAMP TWO ITEM #: 4 This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclu	RAIL 1-Z802 O/T 2 For e Federal Automobile ine, License, and Title Fees,	OTAL MSRP \$48,1 Whether you decide to lease of vehicle, you'll find the choices for you. See your dealer for de www.ford.com/finance. PJ081 N RB 2X 415 000406 09 08	or finance your s that are right stails or visit	WWW.safercar.gov or 1-888-327 2FMPK4K90RBA31526 WARNING: Operating, servicing and maintaining a particular of the state of California to cause carr Vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause carr To minimize exposure, avoid breathing exhaust, do not idle to vehicle in a well-ventilated area and wear gloves or wash yo For more information go to www.P65Warnings.ca.gov/passe

