| HRM-006954 <sub>CA</sub>   | 9-NORMAL, NB, 006954, RB121 <b>18</b>  | 3341   | CERT CERT CE  | TRD RAMP BUMP C   | CAMP BOOK EXFL ROTA   | 0(<br>1525,   |
|--|--|--|---|---|---|---|
|  | 121" WHEELBASE CO<br>2.0L ECOBOOST ENGINE INTI<br>8-SPD AUTO TRANSMISSION E  |  | RR A57988<br>ERIOR<br>CARBONIZED GRAY METALLIC<br>ERIOR<br>BLACK ONYX TRIM  |   | EPA<br>DOT Fuel Econ<br>Fuel Economy  | Nomy and Env<br>MPG Small Pickup<br>MPG. The be   |
| EXTERIOR<br>• DOOR HANDLES - BLACK<br>• EASY FUEL® CAPLESS FILLER<br>• ENCLOSED BED STORAGE<br>• FLEXBED™ STORAGE SYSTEM<br>• HEADLAMPS - WIPER ACTIVATED<br>• HEADLAMPS - UED AUTO ON/OFF<br>• POWER MIRRORS<br>• POWER TAILGATE LOCK<br>• WIPERS- INTERMITTENT   | INTERIOR<br>• 1-TOUCH DOWN DRIVER WINDOW<br>• 2ND ROW BENCH FLIP-UP W/<br>UNDER-SEAT STORAGE<br>• CRUISE CONTROL<br>• DUAL SLIDING SUNVISORS<br>• MANUAL A/C, SINGLE ZONE<br>• MAP POCKETS-PASSENGER<br>• PARTICULATE AIR FILTER<br>• POWER LOCKS AND WINDOWS<br>• POWER LOCKS AND WINDOWS<br>• POWERPOINTS - 12V<br>• ROTARY GEAR SHIFT DIAL W/<br>SELECTABLE DRIVE MODES<br>• UNIQUE CLOTH BUCKET SEATS<br>• USB A AND C<br>• VINYL SOFT CONSOLE LID | <ul> <li>EUNCTIONAL</li> <li>8.0" CTR STACK TOU</li> <li>AM/FM STEREO W/6</li> <li>APPLE CARPLAY™ A<br/>ANDROID AUTO™</li> <li>BATTERY SAVER FEA</li> <li>CARGO BOX TIE DOW</li> <li>ELECTRIC PARKING</li> <li>ELECTRONIC PWR A</li> <li>FADE-TO-OFF INTER</li> <li>FORDPASS™ CONNE</li> <li>PRE-COLLISION ASS</li> <li>REAR VIEW CAMERA</li> <li>REMOTE KEYLESS E</li> <li>REMOTE START- FOR</li> </ul> | SPEAKERS<br>ND<br>ATURE<br>ATURE<br>ATURE<br>ATURE<br>SECURILOO<br>PERIMETER<br>SECURILOO<br>TIRE PRESS<br>BRAKE<br>SST STEER<br>IOR LIGHT<br>SYR/36,000<br>SYR/60,000<br>SYR/60,000<br>SYR/60,000<br>SYR/60,000<br>SYR/100,000<br>NTRY<br>-COMPONE | SAFETY CANOPY®<br>DER CHIME<br>LD SAFETY SYSTEM   | combined city/hwy<br>4.8 gallons per 10<br>Annual fuel COS<br>\$2,55<br>Actual results will vary for many<br>vehicle. The average new vehicle<br>based on 15,000 miles per year a<br>emissions are a significant cause  | 50 Fuel Economy 8   |
| INCLUDED ON THIS VEHICLE<br>EQUIPMENT GROUP 300A<br>OPTIONAL EQUIPMENT/OTHER<br>235/65 R17 A/T TIRES<br>TREMOR OFF ROAD PACKAGE<br>.FLR LNRS W/CARPETED MATS<br>.FULL SIZE SPARE TIRE<br>.TRAILER HITCH RECEIVER<br>.17" MACH DARK ALUM WHEEL<br>XLT LUXURY PACKAGE<br>.POWER 8-WAY DRIVER SEAT<br>.BEDLINER-MODULAR HARD DROP-IN<br>FORD CO-PILOT380<br>50 STATE EMISSIONS<br>FRONT LICENSE PLATE BRACKET | (MSRP)<br>2,220.00<br>NO CHARGE<br>3,495.00<br>2,275.00<br>650.00<br>NO CHARGE<br>NO CHARGE  |  | PRICE INFORMATION<br>BASE PRICE<br>TOTAL OPTIONS/OTHER<br>TOTAL VEHICLE & OPTIONS/OT<br>DESTINATION & DELIVERY  | (MSRP)<br>\$26,315.00<br>8,640.00<br>THER 34,955.00<br>1,595.00   | fueleconon         Calculate personalized estimate         GOVERNMEN         Overall Vehicle Score         Based on the combined ratings         Should ONLY be compared to         Frontal       Drive         Crash       Pass         Based on the risk of injury in a         Should ONLY be compared to         Side       Frontal         Crash       Rear         Based on the risk of injury in a         Should ONLY be compared to         Side       Frontal         Crash       Rear         Based on the risk of injury in a         Based on the risk of injury in a         Based on the risk of injury in a         Rollover         Based on the risk of rollover in         Star ratings range from 1 to         Source: National Hight | The section of similar size a single-vehicle crash.                                     |
|  | RH27   | RAIL<br>71-9948 O/T 2  | Whether you decid   | \$36,550.00<br>de to lease or finance your<br>the choices that are right<br>dealer for details or visit<br>nance. | WARNING: Operating, se vehicle can expose you to  | BFTTW8C95RRA57988<br>ervicing and maintaining a pass<br>o chemicals including engine ep |
|  | This label is affixed pursuant to<br>Information Disclosure Act. Ga<br>State and Local taxes are not ir<br>options or accessories are not  | asoline, License, and Title Fees,<br>ncluded. Dealer installed   | RB121 N RB 2X 425 00  |   | lead, which are known to the Sta<br>To minimize exposure, avoid bre<br>vehicle in a well-ventilated area a<br>For more information go to www.   | athing exhaust, do not idle the   |

