HRM-007213 _{FL}	9-NORMAL, NB, 107213, SD071 40	55	UTC U W FL CERT CERT CERT TRD RAMP BUMP C	CAMPBOOKEXFLROTA 00 3298/
VEH	ICLE DESCRIPTION MAVERICK 2025 XLT FWD 121" WHEELBASE 2.5L HYBRID ENGINE POWER-SPLIT ELECTRIC CVT	EXTERIOR ERUPTION GR INTERIOR NAVY PIER - M BATTERY SAVER FEATURE • ELECTRIC PARKING BRAKE • ELECTRONIC PWR ASST STEER • FORDPASS™ CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM • INTELL ACCESS W/PUSH START • PRE-COLLISION ASSIST W/AEB • REAR VIEW CAMERA • SELECTABLE DRIVE MODES • SYNC®4 W/EVR & 13.2" SCRN	SR A78617 SR A78617 EEN ED SLATE TRIM SAFETY/SECURITY AIRBAGS - SAFETY CANOPY® - BELT-MINDER CHIME - LATCH CHILD SAFETY SYSTEM - PERIMETER ALARM - SECURILOCK® ANTI-THEFT SYS - TIRE PRESSURE MONIT SYS MERANTY - SYR/60,000 BUMPER / BUMPER - SYR/60,000 POWERTRAIN - SYR/60,000 POWERTRAIN - SYR/60,000 POWERTRAIN - SYR/60,000 POWERTRAIN - SYR/60,000 POWERTRAIN - SYR/60,000 HYBRID UNIQUE - COMPONENTS IF EQUIPPED MATION NS/OTHER - 2,685.00 - 2,685.00 - 2,180.00	EPA DOT Fuel Economy Fuel Economy Small Pickup Fuel Economy Small Pickup Image: State of the state o
				Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size an Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover ★ ★ ★ Based on the risk of rollover in a single-vehicle crash.
	RAMP ONE	TOTAL	MSRP \$33,775.00	Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Adminis www.safercar.gov or 1-888-327-423 3FTTW8H36SRA78617
	RAMP TWO	RAIL Ford Credit	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ext lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to t Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	the Federal Automobile oline, License, and Title Fees, luded. Dealer installed SD071 N	RB 2X 550 007213 04 07 25	lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

