Cord 22 X 2	CRIPTION ANSIT 023 XLT WAGON LWB LT 6 PASSENGER 0L GDI 14 ENGINE SPD AUTO TRANSAXL	I INT	P1 TERIOR MAGNETIC METALLIC ERIOR EBONY CLOTH SEATS		EPA DOT Fuel Economy and Er Fuel Economy R 2 6 MPG Spec. Pur 28 MPG. MPGe.	
COLOR +6-W BUMPERS - BODY COLOR MAN DOOR HANDLES - BODY COLOR - AUT DOORS - DUAL SLIDING SIDE CEN LIFTGATE W/ FXD GLASS REAR STO FOG LAMPS - AUTO GLASS REAR - DU/ GRILLE - 5 BAR, CHROME - DU/ HEADLAMPS - AUTO HIGH BEAM - FLO POWER ADJ/HEATED/POWER - OVE FOLD EXTERIOR MIRRORS - POW WIPERS - RAIN-SENSING - SM/ STE WIN FRO INCLUDED ON THIS VEHICLE (M ORDER CODE 210A OPTIONAL EQUIPMENT/OTHER WIFI 4G LTE HOTSPOT DELETE 50 STATE EMISSIONS NO CH	AND 3RD ROW SEATS AY POWER DRIVER/4-WAY IUAL PASSENGER SEATS O-DIM REARVIEW MIRRO ITER CONSOLE W/ARMRE RAGE & 2 CUPHOLDERS IL-ZONE ELECTRONIC O CLIMATE CONTROL OR COVERING - CARPETE RHEAD STOWAGE SHELF VERPOINTS - 12V (3) ART CHARGING USB PORT ERING - TILT/TELESCOPIC DOWS-1-TOUCH UP/DOW NT/REAR	FRONT WHEEL DRIV R FUEL TANK15.8 (ST, HILL START ASSIST PHONE WIRELESS (PRE-COLLISION AS REAR VIEW CAMER ED REMOTE KEYLESS REVERSE SENSING SYNC® 3 (2)	NFO SYS) • ADN DISC/ABS • AIR VE • AIR GAL • AIR CHRGING PAD SIST W/AEB • EMI A • MY ENTRY • SEC SYSTEM • TIR • SYSTEM • TIR • SYSTEM • SYF	CURILOCK PASS ANTI THEFT E PRESSURE MONITOR SYS (RANTY 3/36,000 BUMPER / BUMPER 8/60,000 POWERTRAIN 8/60,000 ROADSIDE ASSIST (MSRP) 1 (MSRP) 1 (ST,715.00 (R 120.00 (ONS/OTHER 37,835.00	fueleconomy.gov Calculate personalized estimates and compare vehicles	
	RAMP ONE CD4C RAMP TWO	CONVOY ITEM #: 11-S500 O/T 2	Gird vehicle, yo	P \$39,730.00 you decide to lease or finance your ou'll find the choices that are right ee your dealer for details or visit l.com/finance.	vehicle can expose you to chemicals including engine	
	Information Disclosure State and Local taxes	I Irsuant to the Federal Automobile e Act. Gasoline, License, and Title Fees, are not included. Dealer installed s are not included unless listed above.		335 002012 01 09 24	lead, which are known to the State of California to cause cand To minimize exposure, avoid breathing exhaust, do not idle th vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passen	

