			<b>7429</b>		CAMP BOOK EXFL ROTA	2974/3911	
145" \ 5.0L \			ERIOR XFORD WHITE RIOR	рк <b>E73145</b>	EPA DOT Fuel Econom	70 MPG. The best vehic MPGe. Values are based	
STANDARD EQUIPMENT INCLUDED AT NO EXTRA C   EXTERIOR INTERIOR   • DAYTIME RUNNING LAMPS • 4" PROD   • EASY FUEL® CAPLESS FILLER • CRUISE   • FULLY BOXED STEEL FRAME • DOOR LC   • HALOGEN HEADLAMPS • DUAL SU   • HEADLAMPS - AUTO HIGH BEAM • ILLUMIN   • HEADLAMPS - AUTOLAMP • MESSAG   • (ON/OFF) • LOCKING REMOVABLE TAILGATE	AUCTIVITY SCREEN ONTROL CKS - POWER WISORS TED ENTRY CTR: OUTSIDE TEMP, 5, TRIP COMPUTER DINTS - 12V SSCOPE STR COLUMN		SYSTEM • AIRBAGS - SAFETY CANOPY®   T™ 4G • CTR HIGH MOUNT STOP LAMP   CS MODEM • PERIMETER ALARM   • SOS POST-CRASH ALERT SYS™   • TIRE PRESSURE MONIT SYS   AKING   IST W/AEB   ND   • SYR/60,000 BUMPER / BUMPER   • 5YR/60,000 ROADSIDE ASSIST				
REAR-WINDOW DEFROSTER SIRIUS XM W/ 360L .PRIVACY GLASS W/REAR DEFROSTE 50 STATE EMISSIONS TRAILER TOW PACKAGE .INTEGRATED TRAILER BRAKE CONT FOG LAMPS 20" 6-SPOKE MAGNETIC PKT WHLS STX SPORT CLOTH 40/CON/40 FLEX FUEL VEHICLE		G			Frontal D   Crash P   Based on the risk of injur Should ONLY be compared   Side F   Crash R   Based on the risk of injur R   Based on the risk of injur R   Based on the risk of injur R   Based on the risk of rollo Star ratings range from   Source: National R	Priver Passenger ty in a frontal impact. ted to other vehicles of similar size and weight. Front seat Rear seat ty in a side impact. The seat ty in a	
	ITEM #:	e Federal Automobile ine, License, and Title Fees,	(Jord) ver	ISRP \$53,790.00 ether you decide to lease or finance you icle, you'll find the choices that are righ you. See your dealer for details or visit w.ford.com/finance.	Nt WARNING: Operative Vehicle can expose lead, which are known to the to minimize exposure, aver vehicle in a well-ventilated	<b>1FTFW1E58PKE73145</b> ing, servicing and maintaining a passenger vehic you to chemicals including engine exhaust, carb he State of California to cause cancer and birth d id breathing exhaust, do not idle the engine exce area and wear gloves or wash your hands freque www.P65Warnings.ca.gov/passenger-vehicle.	

2202306147429

