HRM-000175 IL	9-NORMAL, NA, 200175, KC012	)171		IL UMP CAMP BOOK EXFL
VEHIC	CLE DESCRIPTION <b>SUSION</b> 2019 FUSION SE FWD 5-PASSENGER 1.5L ECOBOOST ENGINE 6-SPD AUTO TRANSMISSION	EXTERIOR RUBY RED TI INTERIOR EBONY CLOT AM/FM, MP3, 6-SPEAKERS BLIS (BLIND SPOT INFO SYS) FORDPASS'M CONNECT 4GWI-F HOTSPOT TELEMATICS MODEM LANE-KEEPING SYSTEM/ALERT PRE-COLLISION ASSIST W/AEB PUSH-BUTTON START REAR VIEW CAMERA REMOTE KEYLESS ENTRY REVERSE SENSING SYSTEM SECURICODE KEYLESS KEYPAD SIRIUSXM® - SVC N/A AK&HI SYNC3® 8" SCRN W/APPLINK® PRICE INFO	CERT CERT CERT TRD RAMP BI KR 213976 INTED CLEARCOAT TH SEATS SATECTY/SECURITY • AVANCETRAC ESC • AIRBAG-DRIVER/PASS KNEE • AIRBAGS - DUAL STAGE FRONT • AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT • AIRBAGS - SIDE AIR CURTAIN • LATCH CHILD SAFETY SYSTEM • PERIMETER ALARM • SECURILOCK® ANTI-THEFT SYS • TPMS - INDIVIDUAL MARRANTY • SYR/36,000 BUMPER / BUMPER • SYR/60,000 POWERTRAIN • SYR/60,000 ROADSIDE ASSIST	UNIP CAMP BOOK EXFL   EPA FUEL ECONOMY   Fuel Economy   Image: Strategy of the second
				Side Front seat ★ ★ ★   Crash Rear seat ★ ★ ★   Based on the risk of injury in a side impact. ★ ★ ★   Rollover ★ ★ ★   Based on the risk of rollover in a single-vehicle crash.
				Star ratings range from 1 to 5 stars (★★★★), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-423
	RAMP ONE RLK6		L MSRP \$25,510.00 Whether you decide to lease or finance you	3FA6P0HD6KR213976
	RAMP TWO	41-Z706 O/T 2 FORD CREDIT	vehicle, you'll find the choices that are righ for you. See your dealer for details or visit www.ford.com/finance.	Nt WARNING: Operating, servicing and maintaining a passer vehicle can expose you to chemicals including engine exhat lead, which are known to the State of California to cause cancer a
	This label is affixed pursuant to Information Disclosure Act. Ga State and Local taxes are not ir options or accessories are not	asoline, License, and Title Fees, ncluded. Dealer installed KC012 N	I RA 2X 950 000175 03 01 19	To minimize exposure, avoid breathing exhaust, do not idle the er vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger-

