| CUA-006865 TX 52 | 2D 099 6B 2 A LABL ADJ COV PRCS | 8 W TX B10 RAMP BUMP | 3FMTK3R47PMB02753 | MUSTANG | SH | 022132 3744/6736 |
|------------------|---|-------------------------|---|--|--|--|
| VEHICL | e description IUSTANG N 2023 premium rwd 5-passenger 72kwh usable std lfp bat single-speed transmissio | | ERIOR (APOR BLUE METALLIC ERIOR BLK PERFORATED ACTI O CHARGER RA M, 10 SPKR (3-YR INC) PEDAL DRV IECT 4GWI-FI ICS MODEM IMPAC CONNECTOR R INDIV CONNECTOR IMPAC CONNECTOR IMPAC CONNECTOR SOS P R INDIV CONNECTOR SOS P R INDIV CONNECTOR SOS P R INDIV CONNECTOR SOS P SR INDIV SOS P SR SYR/60 SYR/60 | /SECURITY ICED SECURITY PACK ICETRAC™ STABILITY/TRACTN CTL 3 - DRIVER KNEE GS - DUAL STAGE FRONT GS - DUAL STAGE FRONT GS - FRT/REAR SIDE T & SIDE AIR CURTAIN DST-CRASH ALERT SYS™ TIRE PRESS MONIT SYS CHILD SAFETY SYSTEM NTY 0,000 BUMPER / BUMPER 0,000 POWERTRAIN 0,000 HV BATT/COMPON (MSRP) \$42,895.00 500.00 S/OTHER 43,395.00 | Fuel Econ Fuel Econ combined cit Driving Ram When fully fuel 0 40 Charge Tim Annual fuel \$700 Actual results will vary your vehicle. The avera are based on 15,000 m emissions are a signific fuelecol Calculate personalize GOVER Overall Vehic Based on the combin Should ONLY be com Side Crash Based on the risk of i Should ONLY be com Side Crash Based on the risk of i Should ONLY be com | Economy and Environm omy MPGe MPGE MPG |
| | RAMP ONE RU78 | | TOTAL MSRP | \$45,195.00 | | www.safercar.gov or 1-888-327-4236 3FMTK3R47PMB02753 |
| | RAMP TWO | 52-0801 O/T 2 | Ford vehicle, you'l | decide to lease or finance your I find the choices that are right our dealer for details or visit m/finance. | vehicle can exp | erating, servicing and maintaining a passenger vehicl ose you to chemicals including phthalates and lead, v ncer and birth defects or other reproductive harm. To |
| | This label is affixed pursuant to the Federal Automobil Information Disclosure Act. Gasoline, License, and Tit State and Local taxes are not included. Dealer installe options or accessories are not included unless listed | | , I384 R 6B 2A8 335 006865 02 22 24 | | California to cause cancer and birth defects or other reproductive harm. To or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle. | |

05/20/2024

