HRM-006564 OR	9-NORMAL, NB, 006564, RD031 13	164	CERT CERT CERT TRD	O RAMP BUMP C	AMP BOOK EXFL ROTA	00 4355,
VEHICL	E DESCRIPTION AVERICK 2024 XLT AWD 121" WHEELBASE 2.0L ECOBOOST ENGINE 8-SPD AUTO TRANSMISSION	EXTERIOR ATLAS BI INTERIOR NAVY PIE • 8.0" CTR STACK TOUCHSCRE • AM/FM STEREO W/6 SPEAKEI • APPLE CARPLAY™ AND ANDROID AUTO™ • BATTERY SAVER FEATURE • CARGO BOX TIE DOWN HOOF • ELECTRIC PARKING BRAKE • ELECTRIC PARKING BRAKE • FADE-TO-OFF INTERIOR LIGH • FORDPASS™ CONNECT • PRE-COLLISION ASSIST W/AE • REAR VIEW CAMERA • REMOTE KEYLESS ENTRY • REMOTE START- FORDPASS	RR A87   LUE METALLIC   ER -MED SLATE TRIM   SER   AIRBAGS - SAFETY C.   BELT-MINDER CHIME   LATCH CHILD SAFETY   PERIMETER ALARM   SECURILOCK® ANTI-   TIRE PRESSURE MON   MARRANTY   SYR/36,000 BUMPER   SYR/60,000 POWERTF   SYR/60,000 POWERTF   SYR/100,000 HYBRID   -COMPONENTS IF EQ   INFORMATION	ANOPY® Y SYSTEM THEFT SYS NT SYS / BUMPER RAIN E ASSIST UNIQUE	EPA Fuel Economy Fuel Economy Fuel Economy Page 25 combined city/hwy 4.0 gallons per 1 Annual fuel CO \$2,35 combined city/hwy 4.0 gallons per 1 Annual fuel CO \$2,25 combined city/hwy 4.0 gallons per 1 Annual fuel CO \$2,35 Correst vill vary for man vehicle. The average new vehic based on 15,000 miles per year emissions are a significant cause fueleconomies per year emiss	A355, nomy and Env MPG Small Pickup MPG. The back 222 29 city highway 100 miles Fuel Economy 8 1 This vehicle emits 356 g 1 This vehicle emits 356 g 2 This vehicle emits 3 2 This vehicle emi
	RAMP ONE				www.sa	to 5 stars ( $\star \star \star \star$ ), wit way Traffic Safety Adminis afercar.gov or 1-888-327-42
	RAMP ONE CA42 RAMP TWO	CONVOY	Whether you decide to lease vehicle, you'll find the choice redit for you. See your dealer for d	s that are right	WARNING: Operating, s	3FTTW8J93RRA87106
	This label is affixed pursuant to t Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	the Federal Automobile oline, License, and Title Fees, Iuded. Dealer installed RD03	31 N RB 2X 425 006564 04 0		lead, which are known to the St	ate of California to cause cance eathing exhaust, do not idle the

