ford.com	2024 F250 SRW 4X4 CREW CA LARIAT 160" WB STYLESIDE 6.7 HI OUTPUT POWER STROK 10-SPEED AUTO TORQSHIFT			Environme
STANDARD EQUIPMENT INCLUDED AT				These ratings are not directly comparabl For information on how to com
EXTERIOR • HEADLAMPS - AUTO HIGH BEAM • HEADLAMPS - AUTOLAMP (ON/OFF) • LED REFLECTOR HEADLAMPS • PICKUP BOX, TIE DOWN HOOKS • POWER SLIDING REAR WINDOW W/DEFROST & PRIVACY TINT • POWER TAILGATE LOCK • POWERSCOPE TT POWER-FOLD MIRRORS, POWER/HEATED • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER PREFERED EQUIPMENT PKG.608A 6.7 HI OUTPUT POWER STROKE 10-SPEED AUTO TORQSHIFT 3.55 ELECTRONIC-LOCKING AXLE FRONT LICENSE PLATE BRACKET ALL WEATHER MATS W/O CARPT MAT SPORT APPEARANCE PACKAGE TREMOR OFF-ROAD PACKAGE 35" OFF ROAD LT285/75R18E AT .SKID PLATES .MACHINED AND PAINT ALUM-18"WH 11000# GVWR PACKAGE 50 STATE EMISSIONS PRO POWER ONBOARD - 2KW POWER MOONROOF TWIN PANEL HIGH CAPACITY TRAILER TOW PKG JACK TAILGATE STEP DUAL BATTERY LEATHER 40/CONSOLE/40 SEAT	INTERIOR • 12" PRODUCTIVITY SCREEN • 120V OUTLET • 170UCH UP/DOWN DR/PASS WIN • DUAL-ZONE ELECTRONIC AUTO CLIMATE CONTROL • LEATHER STEERING WHEEL W/ AUDIO CONTROLS • OUTSIDE TEMP DISPLAY • PARTICULATE AIR FILTER • POWER LOCKS AND WINDOWS • PWR DRIVER AND PASS SEAT • TILT/TELESCOPE STR COLUMN 12,495.00 NO CHARGE NO CHARGE 130.00 2,880.00 4,375.00 NO CHARGE 985.00 1,495.00 NO CHARGE 375.00 NO CHARGE 375.00 NO CHARGE 375.00 NO CHARGE NO CHARGE 0 375.00 NO CHARGE 0 375.00 NO CHARGE NO CHARGE	DESTINATION TOTAL BEF TREMOR W	\$64,740.00 22,735.00 SLE & OPTIONS/OTHER & DELIVERY 1,995.00 FORE DISCOUNTS //TRAILER TOW //SPORT APPRNCE - 570.00	
	RAMP ONE RA5B	TOTAL	MSRP \$88,330.00	1FT8W2BM4REE21006

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

RA5B		
RAMP TWO	RAIL	
	ITEM #: 52-8523 O/T 2	
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		

whether you declue to tease of finalice you vehicle, you'll find the choices that are right (Fird) Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

RE141 N RB 2X 425 003809 05 14 24

05/16/2024

