<b>FLR-000279</b> TX	9-NORMAL,NA,100279,RD181 570	120240429 681 BLEND	1 CMC U CERT CERT CERT TR		CAMP BOOK EXFL ROTA
VEHI	CLE DESCRIPTION MUSTANG 2024 GT COUPE 4-PASSENGER SPORTS CAR 5.0L TI-VCT V8: GT 480HP 6-SPEED MANUAL TRANSMISS	EXTERIOR OXFORD INTERIOR BLACK O NITERIOR BLACK O AM/FM STEREO W/6 SPEAKE ELECTRONIC PWR ASST STE FORD CO-PILOT360™ FORDPASS™ CONNECT 4GW INDEPENDENT REAR SUSPEN INDEPENDENT REAR SUSPEN INTELLIGENT ACCESS W/PUS BUTTON START LIMITED SLIP REAR AXLE REAR PARKING SENSORS REAR VIEW CAMERA SELECTABLE DRIVE MODES SYNC®4 TRACK APPS™	RS RS ADVANCETRACTMES ADVANCETRACTMES ADVANCETRACTMES ADVANCETRACTMES AIRBAG-DRIVER/PA AIRBAGS - DUAL ST AIRBAGS - DUAL ST AIRBAGS - FRONT S MOUNTED SIDE IMF AIRBAGS - SIDE AIF INDIV TIRE PRESS M AIRBAGS - SIDE AIF INDIV TIRE PRESS M LATCH CHILD SAFE PERIMETER ALARM SECURILOCK PASS SOS POST CRASH A WARRANTY - 3YR/36000 BUMPEF - 5YR/60,000 POWER - 5YR/60,000 ROADSI	TO BUMPER TABLET SYS	CAMP BOOK EXFL ROTA Compare the second s
					FrontalDriverNot RateCrashPassengerNot RateBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size atSideFront seatNot RateCrashRear seatNot RateBased on the risk of injury in a side impact.Not RateBased on the risk of injury in a side impact.Not RateBased on the risk of injury in a side impact.Not RateStar ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Adminity www.safercar.gov or 1-888-327-4
	RAMP ONE RK34	тот	TAL MSRP \$43,	970.00	
	RAMP TWO	he Federal Automobile Dine, License, and Title Fees, uded. Dealer installed RD1	Whether you decide to leasy vehicle, you'll find the choi redit for you. See your dealer for www.ford.com/finance. 81 N RA 2X 470 000279 04	ces that are right details or visit	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng

1202404296811

