KTP-000249 _{CA}	9-NORMAL,NB,200249,RB1	52 10659	ULC CERT CERT	UWCA ICERT TRD RAMPBUMPC	CAMPBOOKEXFLROTA 26	0 62
VEHICIES VERICIES VICTOR	SUE DESCRIPTION EXPEDITION EXPEDITION 2024 EXPED. LTD STEE IMITED 7-PASSENGE 3.5L ECOBOOST V6 EX 10SPD AUTO TRANS V CNO EXTRA CHARGE 110V/150W AC POWER OUTH 2ND ROW HEATED SEATS AMBIENT LIGHTING 1HTD LTHR WRAPPED STEEF WHEEL W/MOUNTED CONTF HTD/VENTILATED FRT SEAT PEDALS-PWR ADJ W/MEMO POWERFOLD 3RD ROW SEA POWERFOLD 3RD ROW SEA POWERFOLD 3RD ROW SEA POWERFOLD 3RD ROW SEA POWERFOLD STEATS, DR ME SMART CHRGING USBS-ALL TRI-ZONE AUTO CLIMATE C WINDOWS-1-TOUCH UP/DO FRONT/REAR 995.00 NO CHARGE 995.00	ON ALTH 4X4 R NGINE //SLCTSHFT ET ET ET ET ET ET ET ET ET E	CCERTICERT RE EXTERIOR STAR WHITE MET TRI-CO INTERIOR BLK ONYX LEATHER-TRI CCESS LOCK/ SH-BUTTON START CONTROL (STEM, 12 SPKR TOW PREP PAK YR TRIAL) T360™ ASSIST+ CONNECT 4GWI-FI MATICS MODEM WD SYSTEM T SYSTEM 360L- NA AK&HI (RGING PAD	A39851 A39851 A39851 DAT M SEATS	CAMP BOOK EXFL ROTA Image: Comparison of the comparison	SL 855 855 60 775 75 75 00 9
CCD W/SPORT TUNING SUSP CONTROLTRAC WITH 3.73 ELSD 15.5 LCD SCREEN W/TOUCH CAP FRONT LICENSE PLATE BRACKET	1,495.00 1,500.00 795.00 NO CHARGE				Frontal CrashDriver Passenger* * * *Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size* * * *Side CrashFront seat Rear seat* * * * *	
					Based on the risk of injury in a side impact. Rollover ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), we source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-	wi ini
	RAMP ONE RA84				1FMJU2A85REA39851	
	RAMP TWO	RAIL		decide to lease or finance your find the choices that are right	WADNING: Operating convising and maintaining a no	-

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, van, or off-road vehicle can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

(Ford)

vehicle, you'll find the choices that are right

Ford Credit for you. See your dealer for details or visit

www.ford.com/finance.

RB152 N RB 2X 425 000249 02 15 24

ITEM #:

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

72-8563 O/T 2

