| KTP-000264 99   | <b>41C 093 7B X X</b><br>LABL ADJ COV PRCS E  | 1FTI<br>310 RAMP BUMP  | BF2BA3REC81171   | SUPER  | MAIL  | 022688<br>90/344   |
|---|---|--|--|--|---|--|
|   | ICLE DESCRIPTION<br>SUPER DUTY<br>2024 F250 SRW 4X4 REG CAB<br>XL 142" WB STYLESIDE<br>6.8L DEVCT NA PFI V8 ENGINE<br>10-SPEED AUTO TORQSHIFT-G   | EXTERIO<br>OXFO<br>INTERIOI  | PR<br>PR WHITE   | 81171  |   | r Resources Board  |
| STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE  |   |  |  |  | These ratings are not directly comparable to the U<br>For information on how to compare, plea   |  |
| EXTERIOR<br>• DOOR HANDLES - BLACK<br>• HEADLAMPS - AUTOLAMP<br>(ON/OFF)<br>• TOW HOOKS<br>• TRAILER BRAKE CONTROLLER<br>• TRAILER SWAY CONTROL<br>• TRAILER TOW MIRRORS<br>• WIPERS- INTERMITTENT  | INTERIOR<br>• 4.2" PRODUCTIVITY SCREEN<br>• AIR COND, MANUAL FRONT<br>• CLOTH SUN VISORS<br>• DRIVER SEAT-MANUAL LUMBAR<br>• OUTSIDE TEMP DISPLAY<br>• PARTICULATE AIR FILTER<br>• POWER LOCKS AND WINDOWS<br>• STEERING:TILT/TELESCOPE,<br>CRUISE & AUDIO CONTROLS | FUNCTIONAL<br>• 4-WHEEL ANTILOCK BRAI<br>• FORDPASS™ CONNECT S<br>HOTSPOT TELEMATICS M<br>• HILL START ASSIST<br>• MANUAL LOCKING HUBS<br>• MONO BEAM COIL SPRIN<br>SUSPENSION W/STAB BA<br>• REAR VIEW CAMERA<br>• REMOTE KEYLESS ENTRY<br>• SYNC®4 W/8" SCREEN | GGWI-FI<br>IODEM<br>IODEM<br>IG FRT<br>R<br>Y<br>Y<br>AIRBAGS - SA<br>BELT-MINDEF<br>DRIVER/PASS<br>• SECURILOCK<br>• SOS POST-CF<br>8<br>WARRANTY<br>• 3YR/36,000 BU<br>• 5YR/60,000 PC | C <sup>™</sup> WITH RSC®<br>FETY CANOPY®<br>CHIME<br>CHIME<br>CENGER AIR BAGS<br>® ANTI-THEFT SYS<br>ASH ALERT SYS <sup>™</sup><br>JMPER / BUMPER<br>DWERTRAIN<br>DADSIDE ASSIST | <b>Greenhouse</b><br>A+<br>Cleaner  | the environment. Choose <b>Gas Rating</b> (tailpipe only)<br><b>D</b><br>Using alternative fuels marked a primary contributor to climate change  |
| INCLUDED ON THIS VEHICLE<br>OPTIONAL EQUIPMENT/OTHER<br>PREFERRED EQUIPMENT PKG.600A<br>10-SPEED AUTO TORQSHIFT-G<br>LT245/75R17E BSW ALL-TERRAIN<br>3.73 ELECTRONIC-LOCKING AXLE<br>FRONT LICENSE PLATE BRACKET<br>PLATFORM RUNNING BOARDS<br>10000# GVWR PACKAGE<br>ENGINE BLOCK HEATER<br>50 STATE EMISSIONS<br>SNOW PLOW PREP PACKAGE<br>SPARE TIRE AND WHEEL<br>ROOF CLEARANCE LIGHTS<br>JACK<br>UPFITER SWITCHES<br>410 AMP ALTERNATOR<br>DUAL BATTERY<br>XL CHROME PACKAGE<br>.FOG LAMPS | (MSRP)<br>NO CHARGE<br>165.00<br>430.00<br>NO CHARGE<br>320.00<br>NO CHARGE<br>250.00<br>NO CHARGE<br>95.00<br>165.00<br>115.00<br>210.00<br>225.00   | BA<br>TO<br>TO   | ICE INFORMATION<br>SE PRICE<br>TAL OPTIONS/OTHER<br>TAL VEHICLE & OPTIONS/OTHI<br>STINATION & DELIVERY   | (MSRP)<br>\$47,760.00<br>2,165.00<br>ER 49,925.00<br>1,995.00  | California Air Resour<br>GOVERN<br>Overall Vehicle<br>Based on the combined<br>Should ONLY be compa<br>Frontal<br>Crash<br>Based on the risk of inju<br>Should ONLY be compa<br>Side<br>Crash<br>Based on the risk of inju<br>Rollover<br>Based on the risk of roll<br>Star ratings range fro<br>Source: National | Ces Board based on this vehicle's meas         IMENT 5-STAR SAFETY RATING         Score       Not Rated         Iratings of frontal, side and rollover.         ared to other vehicles of similar size and weight.         Oriver       Not Rated         Passenger       Not Rated         ury in a frontal impact.         ared to other vehicles of similar size and weight.         Front seat       Not Rated         Rear seat       Not Rated |
|   | RAMP ONE RC73 RAMP TWO ITEM #:  | RAIL   | Whether you decide   | 5 <b>1,920.00</b><br>to lease or finance your<br>e choices that are right<br>ler for details or visit  | WARNING: Opera  | 1FTBF2BA3REC81171<br>ting, servicing and maintaining a passenger vehic<br>e you to chemicals including engine exhaust, carb<br>the State of California to cause cancer and birth of  |
|   | This label is affixed pursuant to th<br>Information Disclosure Act. Gaso<br>State and Local taxes are not inclu<br>options or accessories are not inclu   | line, License, and Title Fees,<br>uded. Dealer installed E   | 3595 A 7BX X 425 00026   |  | To minimize exposure, av  | the State of California to cause cancer and birth or<br>oid breathing exhaust, do not idle the engine exc<br>d area and wear gloves or wash your hands frequ<br>o www.P65Warnings.ca.gov/passenger-vehicle.  |

05/22/2024

