KIP-001902 TX 9-NORMAL, NB, 201902, RD022 13518			CERT CERT CERT TRD RAMP BUMP CAMP BOOK EXFL ROTA 1229/3	
	CLE DESCRIPTION SUPER DUT 2024 F350 SRW 4X4 CREW CA XL 176" WB STYLESIDE 6.8L DEVCT NA PFI V8 ENGINE 10-SPEED AUTO TORQSHIFT-C	AB EXTERIOR OXFORD WHI1 E INTERIOR	RE D49680	California Air Resources Board Environmen
STANDARD EQUIPMENT INCLUDED A EXTERIOR • DOOR HANDLES - BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • TOW HOOKS • TRAILER BRAKE CONTROLLER • TRAILER SWAY CONTROL • TRAILER TOW MIRRORS • WIPERS- INTERMITTENT INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT PKG.610A 10-SPEED AUTO TORQSHIFT-G LT245/75R17E BSW ALL-TERRAIN 3.73 RATIO REGULAR AXLE FRONT LICENSE PLATE BRACKET 10900# GVWR PACKAGE 50 STATE EMISSIONS 120V/400W OUTLET BLIS (BLIND SPOT INFO SYSTEM) JACK 190AMP(GAS)/250AMP(6.7L) ALTR REVERSE SENSING SYSTEM 360-DEGREE CAMERA PACKAGE XL DRIVER ASSIST PACKAGE	IND EXTRA CHARGE A.2" PRODUCTIVITY SCREEN A.1R COND, MANUAL FRONT CLOTH SUN VISORS DRIVER SEAT-MANUAL LUMBAR OUTSIDE TEMP DISPLAY PARTICULATE AIR FILTER POWER LOCKS AND WINDOWS STEERING:TILT/TELESCOPE, CRUISE & AUDIO CONTROLS MO CHARGE NO CHARGE NO CHARGE 175.00 NO CHARGE 1,150.00 730.00	<ul> <li>EUNCTIONAL</li> <li>A-WHEEL ANTILOCK BRAKE SYS</li> <li>FORDPASS™ CONNECT 5GW1-FI HOTSPOT TELEMATICS MODEM</li> <li>HILL START ASSIST</li> <li>MANUAL LOCKING HUBS</li> <li>MONO BEAM COIL SPRING FRT SUSPENSION W/STAB BAR</li> <li>REAR VIEW CAMERA</li> <li>REAR VIEW CAMERA</li> <li>SYNC@4 W/8" SCREEN</li> </ul>	\$52,815.00 2,220.00 LE & OPTIONS/OTHER 55,035.00	
	RAMP ONE RA88 RAMP TWO	Ford	MSRP \$57,030.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	<b>1FT8W3BA3RED49680</b>
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not inc options or accessories are not i	the Federal Automobile soline, License, and Title Fees, sluded. Dealer installed RD022 N	RB 2X 425 001902 04 02 24	Tead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger

