CHI-007967 _{NM}	9-NORMAL,NB,107967,RA021 19	90 120240109 5669	UTCUWNMCERTCERTCERTTRDRAMPBUMPCERTCERTCERTCERT	
VEHICL VEHICL	<section-header>E DESCRIPTION CALABRY INFORMATION CONTRAC</section-header>	EXTERIOR STONE BLUE INTERIOR EBONY UNION ON FUNCTIONAL • 4-DR INTELL ACCESS LOCK/ UNLOCK W/PUSH-BUTTON START • AM/FM/MP3, 6 SPEAKERS • BRAKES, 4-WHEEL DISC/ABS • FORD CO-PILOT360™ • FORDPASS™ CONNECT • HILL START ASSIST • REAR PARKING SENSORS • REAR VIEW CAMERA • REFRESH95 • SIDE-WIND STABILIZATION • SIRIUSXM® - SVC N/A AK&HI • SYNC®3 8" SCRN W/APPLINK®	CERT CERT CERT TRD RAMP BUMP(RG A17398 METALLIC UE CLOTH SEATS	CAMP BOOK EXFL ROTA 020 1090/1 EPA DOT Fuel Economy Fuel Economy MPG Standard SUVe MPG. The best 2233 20 200 27 combined city/hwy 20 243 20 combined city/hwy 20 243 20 200 27 combined city/hwy 20 200 27 highway 4.3 gallons per 100 miles 1 Annual fuel Costs 1 \$22,33,500 1 Fuel Economy 1 MPG 1 Standard SUVe 1 Marce Surfer 1
4G LTE WI-FI HOTSPOT CREDIT REAR AUXILIARY CNTRLS CREDIT FRONT LICENSE PLATE BRACKET	- 20.00 - 100.00 NO CHARGE RAMP ONE CA4B RAMP TWO ITEM #:	CONVOY	MSRP \$43,185.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	Should ONLY be compared to other vehicles of similar size and Frontal Driver Crash Passenger Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size and Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Based on the risk of injury in a side impact. Rollover Attack to for the seat Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Administr www.safercar.gov or 1-888-327-423 IFMSK8DH4RGA17398
	This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not in options or accessories are not i	the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed RA021 N	RB 2X 420 007967 01 02 24	lead, which are known to the State of California to cause cancer a To minimize exposure, avoid breathing exhaust, do not idle the en vehicle in a well-ventilated area and wear gloves or wash your ha For more information go to www.P65Warnings.ca.gov/passenger-

1202401095669

