KAN-003210 FL	9-NORMAL, NB, 203210, RA162 <b>1</b>	1193 220240123 BLEND	0738 ULC	CERT CERT TRD R		C AMP BOOK EXFL RO	ΓΑ	0: 3128,
VEHIC	DESCRIPTION -150 2024 F-150 4X2 SUPERCREW 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS E		0738 CERTICERTICERTITED RAMP BUMP CA   RK D33147   RK D33147   RK D33147   RK D33147   GATE BLACK METALLIC GATE BLACK METALLIC RIOR LACK STX CLOTH 40/CON/40   FFIC ALERT ITCH W/ ONNECTOR   FFIC ALERT ITCH W/ ONNECTOR   ECT 5GWI-FI CS MODEM - ADVANCETRAC™ WITH RSC® - AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT   AIRBAGS - SAFETY CANOPY® - CTR HIGH MOUNT STOP LAMP - PERIMETER ALARM - AIRBAGS - SAFETY CANOPY® - CTR HIGH MOUNT STOP LAMP - PERIMETER ALARM   SOS POST-CRASH ALERT SYS™ - STOLEN VEH SVCS: 1 YR PLAN - TIRE PRESSURE MONIT SYS - STOLEN VEH SVCS: 1 YR PLAN - TIRE PRESSURE MONIT SYS   MAND - SYR/36,000 BUMPER / BUMPER - SYR/60,000 POWERTRAIN - SYR/60,000 ROADSIDE ASSIST					
6850# GVWR PACKAGE FRONT LICENSE PLATE BRACKET	1,370.00 NO CHARGE NO CHARGE		TOTAL VEHICLE & O DESTINATION & DEL TOTAL BEFORE STX DISCOUNT TOTAL SAVINGS	IVERY DISCOUNTS	49,600.00 1,995.00 2,000.00 2,000.00	Overall Vehic Based on the combi Should ONLY be co Frontal Crash Based on the risk of Should ONLY be co Side Crash Based on the risk of Rollover Based on the risk of	ned ratings of frontal, mpared to other vehic Driver Passenger injury in a frontal imp mpared to other vehic Front seat Rear seat injury in a side impac	$\begin{array}{c} & & & \\ & & \\ & \\ & \\ & \\ & \\ & \\ & \\ $
	CA14		TOTAL MS	RP \$49,59	5.00			52RKD33147
	RAMP TWO	24-8138 O/T 2	Ford Credit for you	er you decide to lease or , you'll find the choices t . See your dealer for deta ord.com/finance.	hat are right	lead, which are known		rnia to cause cancer
	Information Disclosure Act. C State and Local taxes are not	Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		RA162 N RB 2X 420 003210 01 16 24		To minimize exposure, avoid breathing exhaust, do not idle the e vehicle in a well-ventilated area and wear gloves or wash your he For more information go to www.P65Warnings.ca.gov/passenge		

