3 CVS-002723 _{RI}	9-NORMAL, NB, 302723, LJ103 106	625	CBUURRICERTCERTCERTTRDRAMPBUN	
	ICLE DESCRIPTION ECOSPORT 2020 ECOSPORT SES 4WD 5-PASSENGER 2.0L TI-VCT GDI I-4 ENGINE 6-SPD AUTO TRANS W/SLCTSH	EXTERIOR LIGHTNING BL INTERIOR	LC 395236	
 IRAILER TOW PREP WHING UNIQUE TAILLAMPS WINDSHIELD WIPER DE-ICER INCLUDED ON THIS VEHICLE OPTIONAL EQUIPMENT/OTHER EQUIPMENT GROUP 300A .17" PAINTED MACH ALUM WHEELS .P205/50R17 A/S BSW TIRES 50 STATE EMISSIONS FRONT LICENSE PLATE BRACKET	(MSRP)	SYNC®3 8" SCRN W/APPLINK® VOICE ACTIVATED NAVIGATION PRICE INFOR BASE PRICE TOTAL OPTION	• 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST (MSRP) (MSRP) (MSRP) (%27,380.00 NS/OTHER LE & OPTIONS/OTHER 27,380.00	distributing fuel also cred Actual results will vary for many reasons, including driving com vehicle. The average new vehicle gets 27 MPG and costs \$7,500 based on 15,000 miles per year at \$2.70 per gallon. MPGe is mil- emissions are a significant cause of climate change and smog. Gueleconogy Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFETY Overall Vehicle Score Based on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar size ar Frontal Driver Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar size ar
	RAMP ONE CD4C RAMP TWO ITEM #: This label is affixed pursuant to th Information Disclosure Act. Gase	11-M302 O/T 2	MSRP \$28,625.00 Whether you decide to lease or finance your rehicle, you'll find the choices that are right or you. See your dealer for details or visit yww.ford.com/finance.	Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover ★ ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42 MAJ6S3JL7LC395236 WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine explanation of the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the ovehicle in a well-ventilated area and wear gloves or wash your hor more information go to www.P65Warnings.ca.gov/passenged

