KAN-001858 PA	9-NORMAL, NB, 201858, RB062 116	578 220240215 5899	ULC U W PA CERT CERT TRD RAMP BUMP	C 02 CAMP BOOK EXFL ROTA 1870
VEHI	LE DESCRIPTION -150 2024 F-150 4X4 REGULAR CAB 122" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS	EXTERIOR AGATE BLAC INTERIOR DARK SLATE AM/FM STEREO BLIS W/CROSS-TRAFFIC ALERT CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECTOR CURVE CONTROL FORDPASS [™] CONNECT 5GWI-FI HOTSPOT TELEMATICS MODEM HILL START ASSIST LANE-KEEPING SYSTEM POST-COLLISION BRAKING PRE-COLLISION BRAKING PRE-COLLISION BRAKING PRE-COLLISION BRAKING BASE PRICE SYNC®4 W/EVR & 12" SCREEN PRICE INFO BASE PRICE TOTAL OPTIN	CERT CERT CERT TRD RAMP BUMP (RK D46820 K METALLIC CLOTH 40/20/40 SAPETY/SECURITY ADVANCETRAC™ WITH RSC® AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® AIRBAGS - SAFETY CANOPY® CTR HIGH MOUNT STOP LAMP PERIMETER ALARM SOS POST-CRASH ALERT SYS™ AIRE PRESSURE MONIT SYS DEN EN VEH SVCS: 1 YR PLAN BYR/36,000 BUMPER / BUMPER SYR/60,000 POWERTRAIN BYR/100,000 HYBRID BATTERY MARTION	Image: Stand Stan
				CrashRear seatNot RatBased on the risk of injury in a side impact.★ ★ ★Rollover★ ★ ★Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (★ ★ ★ ★ ★), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42
	RAMP ONE CU2G RAMP TWO ITEM #:	CONVOY	MSRP \$43,680.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	IFTMF1L53RKD46820 WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer
	This label is affixed pursuant to the Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	line, License, and Title Fees, uded. Dealer installed RB062 N	SPECIAL ORDER RB 2X 420 001858 02 06 24	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

2202402155899

