CHI-004172 _{TX}	9-NORMAL,NB,104172,RB281 257	120240308 4826	UTCUWTXCERTCERTCERTTRDRAMPBUMPCERTCERTCERTCERT	022217 CAMP BOOK EXFL ROTA 2137/2249
	CLE DESCRIPTION EXPLORER XLT RWD 2024 EXPLORER XLT RWD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSIO	INTERIOR	RG A32890 MET TRI-COAT LATE ACTIVEX SEAT	EPA DOT Fuel Economy and Environ Fuel Economy Standard SUVs range from MPG. The best vehicle of MPG.
STANDARD EQUIPMENT INCLUDED A EXTERIOR POOR HANDLES - BODY COLOR EASY FUEL® CAPLESS FILLER HEADLAMPS - AUTO LED LED SIGNATURE LIGHTING MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS POWER LIFTGATE PRIVACY GLASS - REAR DOORS REAR INT WIPER/WASH/DFRST REAR SPOILER, BODY COLOR ROOF-RACK SIDE RAILS-BLACK TAILLAMPS-LED TRAILER SWAY CONTROL VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUPMENT GROUP 2020 REMOTE START SYSTEM HEATED STEERING WHEEL B-WAY POWER PASSENGER SEAT COTONAL EQUIPMENT/OTHEN ZOA4 MODEL YEAR STAR WHITE MET TRI-COAT P255/55R20 A/S BSW TIRES 50 STATE EMISSIONS 4G LTE WI-FI HOTSPOT CREDIT FORD CO-PILOT360 ASSIST+ ADAPTIVE CRUISE CONTROL VOICE-ACTV TOUCHSCRN NAV SYS ISASIVE STEERING ASSIST XLT SPORT APPEARANCE PACKAGE 20° CRBN GRAY-PTD 10-SPK WHLS FRONT LICENSE PLATE BRACKET	Indextracharge Provent Service Servic		\$38,670.00	Calculate personalized estimates and compare vehicles GOVERNMENT 5-STAR SAFETY RATING Overall Vehicle Score
	RAMP ONE CH7L	ΤΟΤΑΙ	. MSRP \$47,570.00	www.safercar.gov or 1-888-327-4236 1FMSK7DH3RGA32890
	RAMP TWO ITEM #: This label is affixed pursuant to th Information Disclosure Act. Gaso State and Local taxes are not incluoptions or accessories are not incluoptions or accessories are not incluing	ne Federal Automobile Iline, License, and Title Fees, uded. Dealer installed RB281 N	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RB 2X 425 004172 02 28 24	WARNING: Operating, servicing and maintaining a passenger vehicle vehicle can expose you to chemicals including engine exhaust, carbor lead, which are known to the State of California to cause cancer and birth d To minimize exposure, avoid breathing exhaust, do not idle the engine excervehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

1202403084826

