KTP-002627 TX 9-NORMAL,	NB,102627,PL271 2858	ULCUWTXCERTCERTCERTTRDRAMPBUMP	CAMPBOOKEXFLROTA 018420 201/1906
ford.com 2024 E PLATII 3.5L E 10SPD	EDITION EXPED. PLATINUM 4X2 EX NUM 7-PASSENGER COBOOST V6 ENGINE IN AUTO TRANS W/SLCTSHFT	RE A20571 KTERIOR STAR WHITE MET TRI-COAT TERIOR BLK ONYX LEATHER-TRIM SEATS	EPA DOT Fuel Economy and Environ Fuel Economy MPG. The best vehicle of MPG. The best vehicle of
GRILLE-SILVER LINING MESH HEADLAMPS -WIPER ACTIVATED HEADLAMPS-LED REFLECTOR W/LED SIGNATURE LIGHTING MIRRORS-PWR/HTD/AUTO-FOLD HTD LTHF SIG/APRCH LAMP/MEM/AUTODIM V/CRUISF PANORAMIC VISTA ROOF® HTD/VEN POWER LIFTGATE ROOF-RACK SIDE RAILS-BRGHT RUNNING BOARD-PWR DEPLOY PWR TILT	W AC POWER OUTLET Y HEATED SEATS Y PWR FOLDING SLIDE SEATS LIGHT/ILLUM ENTRY R WRAPPED STR WHL E AND AUDIO CTRLS TILATED FRT SEATS PWR ADJ W/MEMORY DLD 3RD ROW SEAT YTEL STR COL W/MEM E AUTO CLIMATE CTRL	ONTROL • ADVANCETRAC™ WITH RSC® GO MANAGER • AIRBAGS - DUAL STAGE FRONT AT CONTROLS • AIRBAGS - SAFETY CANOPY® 0, 22 SPKR • AIRBAGS - SIDE IMPACT OW PREP PAK • INDIV TIRE PRESS MONIT SYS 3 TRIAL) • LATCH CHILD SAFETY SYSTEM •60™ACTIVE2.0 • PERIMETER ALARM NNECT 4GWI-FI • PERSONAL SAFETY SYSTEM™ ATICS MODEM • REAR OCCUPANT ALERT IGTL SCRN • SOS POST-CRASH ALERT SYS™ 0L- NA AK&HI ¥ATSST SCRN	Image: Strain of the second strain of the
		TOTAL MSRP \$87,630.00	Based on the risk of injury in a side impact. Rollover ★ ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★), with 5 being Source: National Highway Traffic Safety Administration (N www.safercar.gov or 1-888-327-4236 IFMJU1L84REA20571
	RA5B RAIL ITEM #: 52-S000 O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	PL271 N RB 2X 415 002627 11 27 23	WARNING: Operating, servicing and maintaining a passenger vehic vehicle can expose you to chemicals including engine exhaust, carb lead, which are known to the State of California to cause cancer and birth d To minimize exposure, avoid breathing exhaust, do not idle the engine excervehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

05/20/2024

