FLR-000089 _{TX}	9-NORMAL, NA, 100089, PM141 54:	3 120231220 8682 BLEND 8682	CMCUWTXCERTCERTCERTTRDRAMPBUMPC	CAMPBOOKEXFLROTA 2
VEH WEH WEH WEH WEH WEH WEH WEH W	ICLE DESCRIPTION MUSTANG 2024 ECOBOOST COUPE PREM 4-PASSENGER SPORTS CAR 2.3L ECOBOOST 315HP 10-SPEED AUTOMATIC TRANS	MUM EXTERIOR SHADOW BLA INTERIOR BLACK ONYX	CERT CERT CERT TRD RAMP BUMP(R5 121211 ACK CTHR-TRIMMED SAFETY/SECURITY ADVANCETRAC ^{TME} ADVANCETRAC ^{TME} ADVANC	CAMP BOOK EXFL ROTA EPA FUEL ECONOMY Fuel Economy Fuel Economy Page for an and the economy Page for the economy economy Page for the economy Page for the economy economy Page for the economy Page for the economy Page for the economy
OPTIONAL EQUIPMENT/OTHER .3.15 RATIO LIMITED SLIP AXLE 255/40R19 W-RATED TIRE B&O SOUND SYSTEM,12 SPKR SPOILER DELETE MINI SPARE WHEEL & TIRE 19X8.5 PREMIER POLISHED ALUM FRONT LICENSE PLATE BRACKET	NO CHARGE 415.00 895.00 NO CHARGE			Overall Vehicle ScoreNot RayBased on the combined ratings of frontal, side and rollover. Should ONLY be compared to other vehicles of similar sizeFrontalDriverNot RayCrashPassengerNot RayBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar sizeNot RayBased on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of similar sizeNot RaySideFront seatNot RayCrashRear seatNot RayBased on the risk of injury in a side impact.Not RayBased on the risk of rollover in a single-vehicle crash.Not RayStar ratings range from 1 to 5 stars (*****), w Source: National Highway Traffic Safety Admin www.safercar.gov or 1-888-327-4
	RAMP ONE RH80	ΤΟΤΑΙ	. MSRP \$42,350.00	1FA6P8TH8R5121211
	RAMP TWO	the Federal Automobile oline, License, and Title Fees, Juded. Dealer installed PM141 N	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RA 2X 445 000089 12 14 23	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine of lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passeng

1202312208682

