KAN-003071 <sub>TX</sub>	9-NORMAL, NB, 203071, RB052 850	)9 220240213 364	O CERT CERT CERT TR		C C CAMP BOOK EXFL ROTA	02 1283,
VEHIC	LE DESCRIPTION -150 2024 F-150 4X4 SUPERCREW 145" WHEELBASE 5.0L V8 ENGINE ELEC TEN-SPEED AUTO TRANS	EXTERIOR AGATE B INTERIOR BLACK S EUNCTIONAL • AM/FM STEREO • BLIS W/CROSS-TRAFFIC ALE • CLASS IV TRAILER HITCH W/ SMART TRLR TOW CONNECT • CURVE CONTROL • FORDPASS <sup>™</sup> CONNECT 5GW HOTSPOT TELEMATICS MODI • HILL START ASSIST • LANE-KEEPING SYSTEM • POST-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION BRAKING • PRE-COLLISION ASSIST W/AI • REVERSE SENSING AND REAR VIEW CAMERA • SELECTSHIFT® • SYNC®4 W/EVR & 12" SCREE BASE F TOTAL TOTAL	3640   CERT CERT CERT TRD RAMPBUMPC     RK D319502     CERT CERT CERT TRD RAMPBUMPC     RK D319502     CERIOR     CATE BLACK METALLIC     ERIOR     CACK STX CLOTH 40/CON/40     STEM     AFFIC ALERT     HICH W/     CONNECTOR     HICT SGWI-FI     ASS MODEM     STEM     STEM RAKING     SIST W/AEB     AND     AND <		AMPBOOK EXFLENTA 1283 FOR FUEL ECONOMY Fuel Economy Fuel Economy MPG MPG MPG MPG MPG MPG MPG MPG	
.275/60R20 BSW ALL-TERRAIN 3.31 RATIO REGULAR AXLE 7100# GVWR PACKAGE FRONT LICENSE PLATE BRACKET 50 STATE EMISSIONS	NO CHARGE NO CHA	STX E TOTA	TAL MSRP \$53,	- 2,000.00 - 2,000.00 ,475.00 se or finance your ices that are right	Based on the risk of injury in a frontal impact. Should ONLY be compared to other vehicles of simil Side Front seat Crash Rear seat Based on the risk of injury in a side impact. Rollover Based on the risk of rollover in a single-vehicle crash Star ratings range from 1 to 5 stars (* * * * Source: National Highway Traffic Safety www.safercar.gov or 1-888 IFTFW2L52RKD31 WARNING: Operating, servicing and maintaining vehicle can expose you to chemicals including of	lar size a lar size a lar size a $( \star )$ h. $( \star )$ , wit Adminis 8-327-42 1952
	This label is affixed pursuant to th Information Disclosure Act. Gase State and Local taxes are not incl options or accessories are not in	line, License, and Title Fees, uded. Dealer installed RB0	52 N RB 2X 420 003071 02	2 05 24	lead, which are known to the State of California to caus To minimize exposure, avoid breathing exhaust, do no vehicle in a well-ventilated area and wear gloves or wa For more information go to www.P65Warnings.ca.gov/	ise cance ot idle the ash your l

2202402133640

06/02/2024

