SUPER DUTY

2024 F550 4X4 CREW CHASSIS XL 203" WB CHASSIS CAB 6.7L POWER STROKE V8 DIESEL

10-SPEED AUTO TORQSHIFT

4.2" PRODUCTIVITY SCREEN

AIR COND, MANUAL FRONT

OUTSIDE TEMP DISPLAY

PARTICULATE AIR FILTER

UPFITTER SWITCHES

BLACK VINYL FLOOR COVERING

POWER LOCKS AND WINDOWS

STEERING:TILT/TELESCOPE,

CRUISE & AUDIO CONTROLS

VEHICLE DESCRIPTION

INTERIOR

FD

ford.com

• HEADLAMPS - AUTOLAMP

HEADLAMPS - WIPER ACTIVATED

MIRRORS - HTD, PWR GLASS/

MANUAL-FOLD/TURN SIGNALS

TRAILER BRAKE CONTROLLER

TRAILER TOW WIRE HARNESS

ROOF CLEARANCE LIGHTS

TRAILER SWAY CONTROL

WIPERS- INTERMITTENT

EXTERIOR

(ON/OFF)

TOW HOOKS

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

1FD0W5HT3REG01750

MEDIUM DARK SLATE VINYL

EXTERIOR OXFORD WHITE

INTERIOR

4-WHEEL ANTILOCK BRAKE SYS

FORDPASS™ CONNECT 5GWI-FI

HOTSPOT TELEMATICS MODEM

• JEWEL EFFECT HEADLAMPS

• STABILIZER BAR, FRONT/REAR

REMOTE KEYLESS ENTRY

• SYNC®4 W/8" SCREEN

FUNCTIONAL

HILL START ASSIST

RE G01750

SAFETY/SECURITY

WARRANTY

BELT-MINDER CHIME

ADVANCETRAC[™] WITH RSC[®]

AIRBAGS - SAFETY CANOPY®

DRIVER/PASSENGER AIR BAGS

SECURILOCK® ANTI-THEFT SYS

SOS POST-CRASH ALERT SYS™

3YR/36,000 BUMPER / BUMPER


5YR/60,000 ROADSIDE ASSIST

• 5YR/60,000 POWERTRAIN


030198

EPA DOT Fuel Economy and Environment

(MSRP) fueleconomy.gov \$60,370.00 14,065.00 Calculate personalized estimates and compare vehicles 74,435.00 1,995.00



RAMP ONE		TOTAL MSRP \$76,430.00	1FD0W5HT3REG01750
RAMP TWO	RAIL ITEM #: 21-V133 O/T 2	Scan The QR Code to get more details about this vehicle	WARNING: Operating, servicing and maintaining a pas vehicle can expose you to chemicals including engine e lead, which are known to the State of California to cause cance
This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		B911 A 7BX X 435 000175 06 06 25	To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your For more information go to www.P65Warnings.ca.gov/passeng



1FDOW5HT3 REG01750 NB BU09

ncer and birth defects or other reproductive narm. he engine except as necessary, service your ur hands frequently when servicing your vehicle. nger-vehicle.

Credit Get Pregualified now at www.ford.com/finance