EPA Fuel Economy and Environment

**FUEL ECONOMY RATINGS NOT** 

REQUIRED ON THIS VEHICLE



E-SERIES

2025 E-350 CUTAWAY SRW SRW 138 WB 7.3L V8 PREMIUM-RATED ENG. **ELEC 6-SPD AOD W/TOW-HAUL**  SD **D26345** 

EXTERIOR OXFORD WHITE **INTERIOR MEDIUM FLINT CLOTH** 

## STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

- AUXILIARY FUEL PORT
- BUMPER, BLACK
- HEADLAMPS AUTOLAMP (ON/OFF)
- INTERVAL WIPERS
- LT245/75R16E BSW A/S TIRES
- **SOLAR TINTED GLASS**

## **INTERIOR**

- AIR CONDITIONING
- AM/FM RADIO W/ BLUETOOTH® BLACK VINYL FLOOR COVERING
- GLOVE BOX WITH POWERPOINT
- POWERPOINT 12V (FRONT)
- STEERING TILT/TELESCOPIC
- TACHOMETER
- VINYL FRONT HEADLINER
- VINYL SUN VISORS

## **FUNCTIONAL**

- AUX TRANSMISSION COOLER
- BATTERY 78 AMP-HR • FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT
- FRONT SUSPENSION

### **SAFETY/SECURITY**

- 3 POINT SAFETY BELTS
- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- DRIVER/PASSENGER AIR BAGS
- ELECTRONIC STABILITY CNTRL TIRE PRESSURE MONITOR SYS
- TRACTION CONTROL

## **WARRANTY**


- 3YR/36,000 BUMPER / BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60.000 ROADSIDE ASSIST

fueleconomy.gov Calculate personalized estimates and compare vehicles















RA6K

RAMP ONE

**BAMP TWO** 

RAIL

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

41-0835 O/T 59

TOTAL MSRP

Whether you decide to lease or finance your vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

\$42,400.00

# **SPECIAL ORDER**

R160 R 6B 2X 515 000109 03 24 25

# 1FDWE3FN8SDD26345

**WARNING:** Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.





www.ford.com/help/privacy-terms