				SD D36	6561_	EPA DOT Fuel Econor	ny and En
STANDARD EQUIPMENT INCLUDED AT NO EXTENDADORS     EXTENCE   INTERIOR   INTER	Ford	2025 E-350 CUTAWAY SRW SRW 138 WB	OXFOR				
EXTERIOR INTERIOR EXCIDITIONING 4 MXILLARY FUEL PORT 4 MXILLARY	ford.com		MEDIUM	M FLINT CLOTH			
	EXTERIOR • AUXILIARY FUEL PORT • BUMPER, BLACK • HEADLAMPS - AUTOLAMP (ON/OFF) • INTERVAL WIPERS • LT245/75R16E BSW A/S TIRES	INTERIOR • AIR CONDITIONING • AM/FM RADIO W/ BLUETOOTH® • BLACK VINYL FLOOR COVERING • GLOVE BOX WITH POWERPOINT • POWERPOINT - 12V (FRONT) • STEERING - TILT/TELESCOPIC • TACHOMETER • VINYL FRONT HEADLINER	AUX TRANSMISSION COOLE BATTERY - 78 AMP-HR FLEET TELEMATICS MODEN HILL START ASSIST TWIN I-BEAM INDEPENDEN	ER • 3 POINT SAFETY E • 4-WHEEL ANTI-LO BRAKING SYSTEM • DRIVER/PASSENG • ELECTRONIC STA • TIRE PRESSURE N • TRACTION CONTR WARRANTY	BELTS DCK DISC BER AIR BAGS BILITY CNTRL MONITOR SYS ROL	REQUI	RED O
	OPTIONAL EQUIPMENT/OTHER PREFERRED EQUIPMENT PKG.780A .STANDARD TRIM 7.3L V8 PREMIUM-RATED ENG. 4.10 RATIO REGULAR AXLE X56 HIGH-SERIES EXT UPGRADE PKG POWER EQUIPMENT GROUP REAR VIEW CAMERA W/MIRROR RAW MATERIALS SURCHARGE FRONT LICENSE PLATE BRACKET 10050# GVWR PACKAGE 50 STATE EMISSIONS CRUISE CONTROL MIRRORS,MAN TLR TOW W/PWR GLS 16X7 WHITE PAINTED STEEL WHLS TPMS CLOTH BUCKET SEATS	NO CHARGE NO CHARGE 100.00 600.00 495.00 NO CHARGE NO CHARGE NO CHARGE 240.00 230.00 25.00 NO CHARGE NO CHARGE NO CHARGE	BASE TOTA TOTA DEST	• 5YR/60,000 ROAD	SIDE ASSIST (MSRP) \$37,790.00 1,765.00 39,555.00		
		This label is affixed pursuant to th Information Disclosure Act. Gasol State and Local taxes are not inclu	e Federal Automobile ine, License, and Title Fees,	Credit for you. See your dealer f www.ford.com/finance. SPECIAL ORD 81 R 6B 2X 515 000098 12	ER	WARNING: Operating, servicing vehicle can expose you to cherr lead, which are known to the State of C To minimize exposure, avoid breathing vehicle in a well-ventilated area and we For more information go to www.P65W	licals including engine e California to cause cance exhaust, do not idle the ear gloves or wash your

