SD **D39579**

EXTERIOR OXFORD WHITE **INTERIOR**

E-SERIES

MEDIUM FLINT VINYL

1FDWE3FNXSDD39579

- AIR CONDITIONING
- AM/FM RADIO W/ BLUETOOTH®

RH02

BAMP TWO

- GLOVE BOX W/ 12V PWR PT
- POWERPOINT 12V (FRONT)

• BATTERY - 78 AMP-HR

FUNCTIONAL

- AUX TRANSMISSION COOLER
- FLEET TELEMATICS MODEM
- HILL START ASSIST
- TWIN I-BEAM INDEPENDENT FRONT SUSPENSION

SAFETY/SECURITY

- 3 POINT SAFETY BELTS
- 4-WHEEL ANTI-LOCK DISC BRAKING SYSTEM
- DRIVER/PASSENGER AIR BAGS
- TRACTION CONTROL

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

RAIL

24-0768 O/T 59

This label is affixed pursuant to the Federal Automobile

State and Local taxes are not included. Dealer installed

Information Disclosure Act. Gasoline, License, and Title Fees,

options or accessories are not included unless listed above.

POWER EQUIPMENT GROUP **RAW MATERIALS SURCHARGE** FRONT LICENSE PLATE BRACKET 12500# GVWR PACKAGE **50 STATE EMISSIONS** CRUISE CONTROL MIRRORS, MAN TLR TOW W/PWR GLS FUEL TANK 55 GALLON CAPACITY REAR FRAME CROSSMEMBER DELETE

REMOTE KEYLESS ENT/PANIC ALARM

600.00 NO CHARGE **NO CHARGE** 350.00 **NO CHARGE** 240.00 230.00 90.00 NO CHARGE NO CHARGE **PRICE INFORMATION** BASE PRICE

TOTAL OPTIONS/OTHER

TOTAL VEHICLE & OPTIONS/OTHER DESTINATION & DELIVERY

> **FORD WARRANTY IS VOID IF USED AS AN AMBULANCE**

(MSRP)

\$38,295.00 1,880.00

> 40,175.00 1,995.00

NOT FOR AMBULANCE USE.

EPA Fuel Economy and Environment

FUEL ECONOMY RATINGS NOT REQUIRED ON THIS VEHICLE

fueleconomy.gov Calculate personalized estimates and compare vehicles







1FDWE3FNX SDD39579



\$42,170.00 TOTAL MSRP

Whether you decide to lease or finance your vehicle, you'll find the choices that are right Ford Credit for you. See your dealer for details or visit www.ford.com/finance.

SPECIAL ORDER

R153 R 6B 2X 515 000037 03 13 25

1FDWE3FNXSDD39579

WARNING: Operating, servicing and maintaining a passenger vehicle, pickup truck, v vehicle can expose you to chemicals including engine exhaust, carbon monoxide, pht lead, which are known to the State of California to cause cancer and birth defects or other reproductive narm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle. For more information go to www.P65Warnings.ca.gov/passenger-vehicle.



www.ford.com/help/privacy-terms

