Ford.com	HICLE DESCRIPTION <b>EXPEDITION</b> 2025 EXPED. PLATINUM 4X4 PLATINUM 7-PASSENGER 3.5L H/O ECOBOOST V6 10SPD AUTO TRANS W/SLCTS	EXTERIOR STAR WHIT INTERIOR	SE A25841 E MET TRI-COAT GRAY LTHR-TRIM SE	EPA DOT Fuel Economy and E Fuel Economy MPG. Th
STANDARD EQUIPMENT INCLUDED EXTERIOR 9 360 DEGREE ZONE LIGHTING 9 DOOR HANDLES - BODY COLOR 1 EASY FUEL® CAPLESS FILLER 9 HEAVY DUTY TRAILER TOW 9 PANORAMIC VISTA ROOF® 9 PRIVACY GLASS - REAR DOORS 9 SIGNATURE GRILLE LIGHTING 9 SIGNATURE TAIL LAMPS 1 TRAILER SWAY CONTROL 1 WIPERS - RAIN-SENSING INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 600A 0 TOTONAL EQUIPMENT/OTHER 2025 MODEL YEAR STAR WHITE MET TRI-COAT 9 COP PILOT360 ACTIVE 2.0 PLATINUM ULTIMATE PACKAGE 9 285/40R24 A/S BSW TIRES 2.4" TARNISHED DARK MCH ALM WH MULTI-CONTOUR DRIVER/PASS FIL LNERS RW 1&2 W/O CRPET MAT BLUECRUISE EQUIP: 1 YEAR PLAN DRIVER'S PACKAGE CONNECT PKG: 1YR INCL.	<section-header>AT NO EXTRA CHARGE INDE I 10UCH UP/DOWN DR/PASS WIN ADD EXTRA CHARGE I 200 HEATED SEATS ADD ROW 40/20/40 FLEX SEAT UPOWERFOLD ADD WARGENEN SYSTEM ADD WARGENEN ADD WARGENENEN ADD WARGENENEN ADD WARGENENENEN ADD WARGENENENENENENENENENENENENENENENENENENEN</section-header>	BASE PRIC TOTAL OP TOTAL VEH	WARRANTY • 3YR/36,000 BUMPER / BUMPER • 5YR/60,000 POWERTRAIN • 5YR/60,000 ROADSIDE ASSIST (MSRP)	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE         RA4F         RAMP TWO         ITEM #:         This label is affixed pursuant to Information Disclosure Act. Gas State and Local taxes are not into options or accessories are not into ptions options options options options options options	RAIL       21-Z300 O/T 2       the Federal Automobile soline, License, and Title Fees, cluded. Dealer installed       SD161	L MSRP \$94,150.00 Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	<b>IFMJK1MG8SEA25841</b> WARNING: Operating, servicing and maintaining a p vehicle can expose you to chemicals including engine lead, which are known to the State of California to cause can To minimize exposure, avoid breathing exhaust, do not idle vehicle in a well-ventilated area and wear gloves or wash you For more information go to www.P65Warnings.ca.gov/passe

