| CHI-004391 _{WI} | 9-NORMAL, NB, 104391, SG101 259 | 6 120250720 6129 | UTC U W WI CERTCERTCERT TRD RAMPBUMPCAM | PBOOKEXFLROTABATT 580 |
|---|--|--|---|---|
| Ford ford.com | HICLE DESCRIPTION EXPLORER ACTIVE 4WD 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMISSION | EXTERIOR SPACE WHIT INTERIOR DARK SPACI | SG C54651 TE METALLIC E GRAY CLOTH SEATS | EPA DOT Fuel Economy and Env Fuel Economy MPG. The be |
| STANDARD EQUIPMENT INCLUDED EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER ·P255/65R18 A/S BSW TIRES 2ND ROW CAPTAIN'S CHAIRS 50 STATE EMISSIONS 18" SILVER PAINTED ALUM WHLS MINI SPARE AND JACK KIT FRONT LICENSE PLATE BRACKET | AT NO EXTRA CHARGE PARAMENT PARAME | TOTAL VEH | AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT AIRBAGS - SAFETY CANOPY® INDIV TIRE PRESS MONIT SYS LATCH CHILD SAFETY SYSTEM PERIMETER ALARM PERSONAL SAFETY SYSTEM™ SOS POST-CRASH ALERT SYS™ WARRANTY 3YR/36,000 BUMPER / BUMPER 5YR/60,000 POWERTRAIN 5YR/60,000 ROADSIDE ASSIST (MSRP) DRMATION | Image: Additional Control of Contro of Control of Control of Control of Control of Control |
| | RAMP ONE CE06 | | MSRP \$44,145.00 | 1FMUK8DH4SGC54651 |
| | ITEM #: | | The QR Code to | WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine exl lead, which are known to the State of California to cause cancer |
| | This label is affixed pursuant to the Information Disclosure Act. Gasoli State and Local taxes are not inclu- options or accessories are not inclu- | ine, License, and Title Fees, ded. Dealer installed SG101 N | RB 2X 565 004391 07 10 25 | To minimize exposure, avoid breathing exhaust, do not idle the exposure avoid breathing exhaust, do not idle the exposure in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge |

