CHI-001089 IL	4-REBILL,NB,201089,SA072 8	3542 120241222 219	2 CERTCERTCERT TRD RAMPBUM	
ford.com	IICLE DESCRIPTION EXPLORER ACTIVE 4V 2025 EXPLORER ACTIVE 4V 119" WHEELBASE 2.3L ECOBOOST I-4 ENGINE 10-SPEED AUTO TRANSMIS	CARBON E INTERIOR	SG B28228 NIZED GRAY METALLIC DE GRAY ACTIVEX SEATS	EPA DOT Fuel Economy and Environ   Fuel Economy Standard SUVs range from MPG. The best vehicle restriction
STANDARD EQUIPMENT INCLUDED A EXTERIOR • CLASS III TRAILER TOW PKG • EASY FUEL® CAPLESS FILLER • HEADLAMPS - AUTO LED • MIRRORS-MAN-FOLD DUAL PWR HEATED WITH APPROACH LAMPS • POWER LIFTGATE • PRIVACY GLASS - REAR DOORS • REAR INT WIPER/WASH/DFRST • REAR SPOILER, BODY COLOR • ROOF-RACK SIDE RAILS-BLACK • TAILLAMPS-LED • TRAILER SWAY CONTROL • VARIABLE INTERVAL WIPERS INCLUDED ON THIS VEHICLE EQUIPMENT GROUP 200A OPTIONAL EQUIPMENT/OTHER P255/55R20 A/S BSW TIRES 2ND ROW CAPTAIN'S CHAIRS 50 STATE EMISSIONS PANORAMIC VISTA ROOF 20" NICKEL PAINTED ALUM WHLS ACTIVE COMFORT PACKAGE .REMOTE START SYSTEM .LED FOG LAMPS .UNIVERSAL GARAGE DOOR OPENER .HEATED STEERING WHEEL .LED SIGNATURE LIGHTING .8-WAY POWER PASSENGER SEAT FRONT LICENSE PLATE BRACKET	AT NO EXTRA CHARGE INTERIOR 12.3" LCD DIGITAL CLUSTER 1TOUCH UP/DOWN DR/PASS WIN 3RD ROW - 50/50 FOLD FLAT DUAL ILLUM VIS VANITY MIRR POWER DRIVER'S SEAT POWER PASS SEAT POWER POINTS - 12V ROTARY GEAR SHIFT DIAL 1ILT/TELESCOPING STEERING WWHEEL MOUNTED CONTROLS USB-C - ALL ROWS (MSRP) NO CHARGE 1,695.00 1,395.00 3,360.00	BASE I TOTAL TOTAL	Image: Stress of the stres	Image: State of the risk of injury in a side impact.   Side Front seat   Side Front seat   Side Front seat   State on the risk of injury in a side impact.   Should ONLY be compared to other vehicles of similar size and weight.
	RAMP ONE CIO6 RAMP TWO	CONVOY	TAL MSRP \$49,900.00 Whether you decide to lease or finance you vehicle, you'll find the choices that are right credit for you. See your dealer for details or visit www.ford.com/finance.	ht MADNINC: Operating convising and maintaining a personger vahial
	State and Local taxes are no	Gasoline, License, and Title Fees,	72 R RB X 545 001089 01 07 25	lead, which are known to the State of California to cause cancer and birth do To minimize exposure, avoid breathing exhaust, do not idle the engine exce vehicle in a well-ventilated area and wear gloves or wash your hands freque For more information go to www.P65Warnings.ca.gov/passenger-vehicle.

